

## VALDEZ

**ROBE LAKE SPB** (L93) 6 W UTC-9(-8DT) N61°05.23' W146°08.64'

ANCHORAGE

39 NOTAM FILE JNU

**WATERWAY E-W:** 4000X200 (WATER)

**WATERWAY N-S:** 2000X200 (WATER)

**SERVICE:** FUEL JET A

**SEAPLANE REMARKS:** Unattended. No dock facilities, seaplane beaching area is used by recreational boaters and swimmers.

Use extreme caution when operating at the seaplane base. Steel bars protruding from the shoreline and water near the shore line.

**AIRPORT MANAGER:** 907-831-1386

**COMMUNICATIONS:** CTAF 122.9

**COMM/NAV/WEATHER REMARKS:** For a toll free call to Juneau FSS dial 1-866-297-2236.

**THOMPSON PASS** (K55) 17 E UTC-9(-8DT) N61°10.64' W145°41.31'

ANCHORAGE

2080 NOTAM FILE JNU

**RWY 05-23:** 2530X9 (TURF-GRVL)

**RWY 05:** Brush.

**RWY 23:** Brush.

**AIRPORT REMARKS:** Unattended. PPR for ops – amgr. Rwy 05-23 unsafe for Indg, tkof or TGL due to debris on rwy – amgr. Rwy cond unmnt: rcmd visual insp prior to use. High trrn all quads. Exp turbulent wind. Unctld vehicle tfc on rwy. Rwy end 23: Pwr line crosses hill on apch end. Rwy end 05: first 300 ft soft & rutted. 1 ft grass & brush first 1200 ft; remainder 4 ft brush. Rwy 05-23: E side 9 ft usbl; remainder overgrown with 4 ft brush. Rwy 05-23: 4 ft brush E half of rwy; strip 10 ft by 2270 ft E side unusbl; sfc soft aft rain; loose gravel & 6 in brush W half of rwy; slight rise each end.

**AIRPORT MANAGER:** (907) 269-8508

**COMMUNICATIONS:** CTAF 122.9

**RCO 122.55** (JUNEAU RADIO)

**RADIO AIDS TO NAVIGATION:** NOTAM FILE VDZ.

**MINERAL CREEK NDB (MHW)** 524 MNL N61°07.45'  
W146°21.13' 061° 19.6 NM to fld. 21/19E.

NDB unusable:

320°-010° byd 15 NM

**COMM/NAV/WEATHER REMARKS:** For a toll free call to Juneau FSS dial 1-866-297-2236.

