COLORADO 281

HAYDEN

YAMPA VALLEY (HDN)(KHDN) 2 SE UTC-7(-6DT) N40°28.87′ W107°13.06′

CHEYENNE H-3E, L-9E, 11E IAΡ

WICHITA

RWY 10-28: H10000X150 (ASPH-GRVD) S-75, D-170, 2D-260

6606 B ARFF Index—See Remarks NOTAM FILE HDN

RWY 10: MALSF, PAPI(P4L)—GA 3.0° TCH 52', Thid dspicd 510'.


Rgt tfc. RWY 28: REIL, PAPI(P4L)—GA 3.5° TCH 54', P-line, 0.3% down.

RUNWAY DECLARED DISTANCE INFORMATION

RWY 10: TORA-10000 TODA-10000 ASDA-10000 LDA-9490 RWY 28: TORA-10000 TODA-10000 ASDA-10000 LDA-10000

SERVICE: FUEL 100LL, JET A 0X3, 4 LGT ACTIVATE MALSF Rwy 10; REIL Rwy 28; PAPI Rwy 10; HIRL Rwy 10-28-CTAF. Rwy 28 PAPI does not provide obst clearance byd 4 NM from thld.

AIRPORT REMARKS: Attended 1300-0300Z‡, Class I, ARFF Index C from Dec-Mar. ARFF Index B from Apr-Nov. Possible severe winter conditions from Oct-Apr. Check NOTAMS for arpt conditions. No arpt information nor snow removal guaranteed during hrs of nonattendance. CLOSED to unscheduled air carrier ops with more than 30 passenger seat except PPR; call UNICOM 970-819-1333. Large flocks of sandhill cranes around arpt in spring and fall. All acft report 10 minutes prior to tkf/ldg on 123.0-monitor frequency 24 hrs, PAEW on rwy. Between 1300-0300Z‡ ctc UNICOM prior to all tkfs and Idgs for PAEW advisories. During snow season ctc



UNICOM. Request all acft departing Rwy 28 make right or left turnout as soon as safety permits after tkf to avoid town of Hayden and comply with noise abatement procedures. Cold temperature rstd arpt. Alt correction required at or blo -30C. Ldg fee for acft 12,500 pounds and over.

AIRPORT MANAGER: 970-276-5004

WEATHER DATA SOURCES: AWOS-3PT 119.275 (970) 276-3690.

COMMUNICATIONS: CTAF/UNICOM 123.0

HAYDEN RCO 122.25 (DENVER RADIO)

DENVER CENTER APP/DEP CON 120.475

AIRSPACE: CLASS E svc 1400-0400Z‡; other times CLASS G.

RADIO AIDS TO NAVIGATION: NOTAM FILE DEN.

HAYDEN (H) VORW/DME 115.6 CHE Chan 103 N40°31.20′ W107°18.29′ 106° 4 6 NM to fld 7271/14F

ILS/DME 109.9 I-HDN Chan 36 Rwy 10. Class IB. ILS is unmonitored.

HOLLY (KØ8) 1 S UTC-7(-6DT) N38°02.11′ W102°07.00′

3399 NOTAM FILE DEN

RWY 17-35: 4140X40 (GRVL-DIRT) LIRL(NSTD)

RWY 17: TRCV(TRIL)-GA 3.0°. Tree. RWY 35: TRCV(TRIL)-GA 3.0°. Fence.

SERVICE: FUEL 100LL LGT Rwy 17-35 has NSTD edge lgts 30' from rwy edge, lgts at varying heights. Rwy 17-35 NSTD LIRL. TRIL Rwys 17 and 35 OTS indef. ACTIVATE NSTD LIRL Rwy 17-35-CTAF.

AIRPORT REMARKS: Attended on call. For attendant call 719-537-6622, dispatch 719-336-3995. For fuel call 719-537-6622. Dispatch 719-336-3995. Rwy soft when wet. Be alert, intensive USAF student training invof Colorado Springs and Pueblo Colorado. Rwy 35 has +30' powerlines 575' north of rwy end 200' left and right of centerline. Rwy 17 has +5' embankment 200' from rwy end obstruction, +10' road 132' from rwy end obstruction, +4' fence 100' from rwy thid obstruction. See Special Notices-USAF 306 FTG Flight Training Areas, Vicinity of Colorado Springs and Pueblo Colorado.

AIRPORT MANAGER: 719-537-6622 COMMUNICATIONS: CTAF/UNICOM 122.8

CLEARANCE DELIVERY PHONE: For CD ctc Denver ARTCC at 303-651-4257.