

## VALDEZ

**ROBE LAKE SPB** (L93) 6 W UTC-9(-8DT) N61°05.23' W146°08.64'

ANCHORAGE

39 NOTAM FILE JNU

**WATERWAY E-W:** 4000X200 (WATER)

**WATERWAY N-S:** 2000X200 (WATER)

**SERVICE:** FUEL JET A

**SEAPLANE REMARKS:** Unattended. No dock facilities, seaplane beaching area is used by recreational boaters and swimmers.

Use extreme caution when operating at the seaplane base. Steel bars protruding from the shoreline and water near the shore line.

**AIRPORT MANAGER:** 907-831-1386

**COMMUNICATIONS:** CTAF 122.9

**COMM/NAV/WEATHER REMARKS:** For a toll free call to Juneau FSS dial 1-866-297-2236.

**THOMPSON PASS** (K55) 17 E UTC-9(-8DT) N61°10.64' W145°41.31'

ANCHORAGE

2080 NOTAM FILE JNU

**RWY 05-23:** 2530X9 (TURF-GRVL)

**RWY 05:** Brush.

**RWY 23:** Brush.

**AIRPORT REMARKS:** Unattended. PPR for all ops—amgr. Rwy 05-23 unsafe for Indg, tkof or TGL due to debris on rwy – amgr. Rwy cond unmt: rcmd visual insp prior to use. High trm all quads. Exp turbulent wind. Unctld vehicle tfc on rwy. Rwy end 23: Pwr line crosses hill on apch end. Rwy end 05: first 300 ft soft & rutted. 1 ft grass & brush first 1200 ft; remainder 10 ft brush. Rwy 05-23: E side 9 ft unusbl; rmng overgrown with 4 ft brush. Rwy 05-23: east half of rwy overgrown 10 ft brush; strip 10 x 2270 ft unusable. West half of rwy loose gravel and small brush to 6 in. Rwy 05-23 soft aft rain, rises slightly at each end.

**AIRPORT MANAGER:** 907-269-8508

**COMMUNICATIONS:** CTAF 122.9

**RCO** 122.55 (JUNEAU RADIO)

**RADIO AIDS TO NAVIGATION:** NOTAM FILE VDZ.

**MINERAL CREEK NDB (MHW)** 524 MNL N61°07.45'

W146°21.13' 061° 19.6 NM to fld. 21/19E.

NDB unusable:

320°-010° byd 15 NM

**COMM/NAV/WEATHER REMARKS:** For a toll free call to Juneau FSS dial 1-866-297-2236.

