JTAT	
ALSEK RIVER (A57) 44 SE UTC-9(-8DT) N59°11.95′ W138°2	6.75′ JUN
53 NOTAM FILE JNU	
RWY 07-25: 1860X12 (TURF)	
RWY 07: Tree.	096° 41.4 NM From C C C C C
RWY 25: Tree.	Yakutat "YAK" VOR/DME
AIRPORT REMARKS: Unattended. Wildlife invof rwy. Erratic winds off mountair	
range east of rwy. Rwy uneven on both sides with several dips over 12"	
Maintain centerline ctl during ldg and tkf. Gully on thld Rwy 07,	
recommend touch down in front of USFS cabin. Rwy 07–25 soft and we	
during Spring and after heavy rains. Rwy 07–25 NSTD markings, thld	
marked with yellow plastic pipes.	00 000 00000 000 000
	0 00 0 0 0 0 0 0 0 0 0 0 0
AIRPORT MANAGER: 907-784-3359	
COMMUNICATIONS: CTAF 122.9	S and a second s
RADIO AIDS TO NAVIGATION: NOTAM FILE YAK.	1860 X 12 00 000
YAKUTAT (H) (H) VORW/DME 113.3 YAK Chan 80 N59°30.65′	
W139°38.89′ 096° 41.4 NM to fld. 41/20E.	
VOR unusable:	
124°-261° byd 22 NM blo 10,000'	
DME unusable:	
124°-261° byd 22 NM blo 10,000′	00 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
COMM/NAV/WEATHER REMARKS: For a toll free call to Juneau FSS dial	
1–866–297–2236.	
<b>DRY BAY</b> (3AK) 44 SE UTC-9(-8DT) N59°09.86' W138°29.33	
33 NOTAM FILE JNU	l
RWY 05-23: 3600X170 (GRVL)	
DWV OF Trees	
RWY 05: Trees.	
<ul> <li>RWY 23: Trees.</li> <li>AIRPORT REMARKS: Unattended. Rwy condition not monitored, recommend present on the rwy. Southwest end of rwy beyond thid has soft sand. V processing plant. Commercial ops may require a commercial use author</li> </ul>	Vindsock 0.2 miles north on the riverbank at t
RWY 23: Trees. AIRPORT REMARKS: Unattended. Rwy condition not monitored, recommend present on the rwy. Southwest end of rwy beyond thid has soft sand. V processing plant. Commercial ops may require a commercial use author 907–697–2230). Helicopter ops are prohibited without a permit from AIRPORT MANAGER: 907-784-3295 COMMUNICATIONS: CTAF 122.9	Vindsock 0.2 miles north on the riverbank at t prization (ctc Glacier Bay National Park the Glacier Bay National Park superintendent
RWY 23: Trees. AIRPORT REMARKS: Unattended. Rwy condition not monitored, recommend present on the rwy. Southwest end of rwy beyond thid has soft sand. V processing plant. Commercial ops may require a commercial use author 907–697–2230). Helicopter ops are prohibited without a permit from AIRPORT MANAGER: 907-784-3295	Vindsock 0.2 miles north on the riverbank at t prization (ctc Glacier Bay National Park the Glacier Bay National Park superintendent.
<ul> <li>RWY 23: Trees.</li> <li>AIRPORT REMARKS: Unattended. Rwy condition not monitored, recommend present on the rwy. Southwest end of rwy beyond thid has soft sand. V processing plant. Commercial ops may require a commercial use author 907–697–2230). Helicopter ops are prohibited without a permit from AIRPORT MANGER: 907-784-3295</li> <li>COMMUNICATIONS: CTAF 122.9</li> <li>COMMUNAV/WEATHER REMARKS: For a toll free call to Juneau FSS dial 1–866–</li> </ul>	Vindsock 0.2 miles north on the riverbank at t prization (ctc Glacier Bay National Park the Glacier Bay National Park superintendent. -297–2236.
RWY 23: Trees. AIRPORT REMARKS: Unattended. Rwy condition not monitored, recommend present on the rwy. Southwest end of rwy beyond thid has soft sand. V processing plant. Commercial ops may require a commercial use author 907–697–2230). Helicopter ops are prohibited without a permit from AIRPORT MANAGER: 907-784-3295 COMMUNICATIONS: CTAF 122.9 COMM/NAV/WEATHER REMARKS: For a toll free call to Juneau FSS dial 1–866– EAST ALSEK RIVER (AK76) 49 SE UTC–9(–8DT) N59°07.58' W	Vindsock 0.2 miles north on the riverbank at t prization (ctc Glacier Bay National Park the Glacier Bay National Park superintendent. -297–2236.
RWY 23: Trees. AIRPORT REMARKS: Unattended. Rwy condition not monitored, recommend present on the rwy. Southwest end of rwy beyond thid has soft sand. V processing plant. Commercial ops may require a commercial use author 907–697–2230). Helicopter ops are prohibited without a permit from AIRPORT MANAGER: 907-784-3295 COMMUNICATIONS: CTAF 122.9 COMMUNICATIONS: CTAF 122.9 COMMUNICATION	Vindsock 0.2 miles north on the riverbank at t prization (ctc Glacier Bay National Park the Glacier Bay National Park superintendent. -297–2236.
RWY 23: Trees. AIRPORT REMARKS: Unattended. Rwy condition not monitored, recommend present on the rwy. Southwest end of rwy beyond thid has soft sand. V processing plant. Commercial ops may require a commercial use author 907–697–2230). Helicopter ops are prohibited without a permit from AIRPORT MANAGER: 907-784-3295 COMMUNICATIONS: CTAF 122.9 COMM/NAV/WEATHER REMARKS: For a toll free call to Juneau FSS dial 1–866– EAST ALSEK RIVER (AK76) 49 SE UTC–9(–8DT) N59°07.58' W	Vindsock 0.2 miles north on the riverbank at t prization (ctc Glacier Bay National Park the Glacier Bay National Park superintendent. -297–2236. V138°24.53' JU
RWY 23: Trees. AIRPORT REMARKS: Unattended. Rwy condition not monitored, recommend present on the rwy. Southwest end of rwy beyond thid has soft sand. V processing plant. Commercial ops may require a commercial use author 907–697–2230). Helicopter ops are prohibited without a permit from AIRPORT MANAGER: 907-784-3295 COMMUNICATIONS: CTAF 122.9 COMMUNICATIONS: CTAF 122.9 COMMUNICATION	Vindsock 0.2 miles north on the riverbank at t prization (ctc Glacier Bay National Park the Glacier Bay National Park superintendent 297–2236. V138°24.53' JUI 101° 44.6 NM From CCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCC
RWY 23: Trees. AIRPORT REMARKS: Unattended. Rwy condition not monitored, recommend present on the rwy. Southwest end of rwy beyond thid has soft sand. V processing plant. Commercial ops may require a commercial use author 907–697–2230). Helicopter ops are prohibited without a permit from AIRPORT MANAGER: 907-784-3295 COMMUNICATIONS: CTAF 122.9 COMM/NAV/WEATHER REMARKS: For a toll free call to Juneau FSS dial 1–866– EAST ALSEK RIVER (AK76) 49 SE UTC–9(–8DT) N59°07.58' W 39 NOTAM FILE YAK RWY 02–20: 1500X10 (TURF) 0.3% up N	Vindsock 0.2 miles north on the riverbank at t prization (ctc Glacier Bay National Park the Glacier Bay National Park superintendent. -297–2236. V138°24.53' JUI 101° 44.6 NM From CCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCC
RWY 23: Trees. AIRPORT REMARKS: Unattended. Rwy condition not monitored, recommend present on the rwy. Southwest end of rwy beyond thid has soft sand. V processing plant. Commercial ops may require a commercial use author 907–697–2230). Helicopter ops are prohibited without a permit from AIRPORT MANAGER: 907-784-3295 COMMUNICATIONS: CTAF 122.9 COMMUNICATIONS: CTAF 122.9 COMMUNICATION	Vindsock 0.2 miles north on the riverbank at t prization (ctc Glacier Bay National Park the Glacier Bay National Park superintendent -297–2236. V138°24.53 'JUI 101° 44.6 NM From C C C C C C C C C C C C C C C C C C C
RWY 23: Trees. AIRPORT REMARKS: Unattended. Rwy condition not monitored, recommend present on the rwy. Southwest end of rwy beyond thid has soft sand. V processing plant. Commercial ops may require a commercial use author 907–697–2230). Helicopter ops are prohibited without a permit from AIRPORT MANAGER: 907-784-3295 COMMUNICATIONS: CTAF 122.9 COMMUNICATIONS: CTAF 122.9 COMMUNICATION	Windsock 0.2 miles north on the riverbank at t         prization (ctc Glacier Bay National Park the Glacier Bay National Park superintendent         -297-2236.         V138°24.53'         JUI         101° 44.6 NM From       C C C C C C C C C C C C C C C C C C C
<ul> <li>RWY 23: Trees.</li> <li>AIRPORT REMARKS: Unattended. Rwy condition not monitored, recommend present on the rwy. Southwest end of rwy beyond thid has soft sand. W processing plant. Commercial ops may require a commercial use author 907–697–2230). Helicopter ops are prohibited without a permit from AIRPORT MANAGER: 907-784-3295</li> <li>COMMUNICATIONS: CTAF 122.9</li> <li>COMMUNICATIONS: CTAF 122.9</li> <li>COMMUNICATIONS: CTAF 122.9</li> <li>COMMUNICATIONS: CAF 12.8</li> <li>CAT 22.9</li> <li>COMMUNICATIONS: CAF 12.8</li> <li>CAT 22.9</li> <li>COMMUNICATIONS: CAF 12.8</li> <li>COMMUNICATIONS: CAF 12.8</li> <li>CAT 22.9</li> <li>COMMUNICATIONS: CAF 12.8</li> <li>CAT 22.9</li> <li>CA</li></ul>	Vindsock 0.2 miles north on the riverbank at t prization (ctc Glacier Bay National Park the Glacier Bay National Park superintendent -297–2236. V138°24.53' JUI 101° 44.6 NM From C C C C C C C C C C C C C C C C C C C
RWY 23: Trees. AIRPORT REMARKS: Unattended. Rwy condition not monitored, recommend present on the rwy. Southwest end of rwy beyond thild has soft sand. V processing plant. Commercial ops may require a commercial use author 907–697–2230). Helicopter ops are prohibited without a permit from AIRPORT MANAGER: 907-784-3295 COMMUNICATIONS: CTAF 122.9 COMM/NAV/WEATHER REMARKS: For a toll free call to Juneau FSS dial 1–866– EAST ALSEK RIVER (AK76) 49 SE UTC–9(–8DT) N59°07.58' W 39 NOTAM FILE YAK RWY 02–20: 1500X10 (TURF) 0.3% up N RWY 02: Trees. RWY 02: Trees. AIRPORT REMARKS: Unattended. Turf rwy soft and wet in spring and after heavy rains. Rwy safety area ground rises and falls over 12°, maintain centerline control. Rwy used by bears and ATV. Cabin at airstrip	Vindsock 0.2 miles north on the riverbank at t prization (ctc Glacier Bay National Park the Glacier Bay National Park superintendent -297–2236. V138°24.53 'JUI 101° 44.6 NM From CCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCC
RWY 23: Trees. AIRPORT REMARKS: Unattended. Rwy condition not monitored, recommend present on the rwy. Southwest end of rwy beyond thild has soft sand. V processing plant. Commercial ops may require a commercial use author 907–697–2230). Helicopter ops are prohibited without a permit from AIRPORT MANAGER: 907-784-3295 COMMUNICATIONS: CTAF 122.9 COMMUNICATIONS: CTAF 122.9 COMMUNICATIO	Vindsock 0.2 miles north on the riverbank at t prization (ctc Glacier Bay National Park the Glacier Bay National Park superintendent. -297–2236. V138°24.53 'JU 101° 44.6 NM From CCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCC
<ul> <li>RWY 23: Trees.</li> <li>AIRPORT REMARKS: Unattended. Rwy condition not monitored, recommend present on the rwy. Southwest end of rwy beyond thid has soft sand. V processing plant. Commercial ops may require a commercial use autho 907–697–2230). Helicopter ops are prohibited without a permit from AIRPORT MANAGER: 907-784-3295</li> <li>COMMUNICATIONS: CTAF 122.9</li> <li>COMMUNICATIONS: CTAF 122.9</li> <li>COMMUNICATIONS: CTAF 122.9</li> <li>COMMUNICATIONS: CTAF 122.9</li> <li>COMM/NAV/WEATHER REMARKS: For a toll free call to Juneau FSS dial 1–866-</li> <li>EAST ALSEK RIVER (AK76) 49 SE UTC-9(-8DT) N59°07.58 ' W 39 NOTAM FILE YAK</li> <li>RWY 02-20: 1500X10 (TURF) 0.3% up N</li> <li>RWY 02: Trees.</li> <li>AIRPORT REMARKS: Unattended. Turf rwy soft and wet in spring and after heavy rains. Rwy safety area ground rises and falls over 12°, maintain centerline control. Rwy used by bears and ATV. Cabin at airstrip maintained by US Forest Svc. Width of path cut through trees 80'. Windsock in fair condition, mounted on spruce tree and partially</li> </ul>	Vindsock 0.2 miles north on the riverbank at t prization (ctc Glacier Bay National Park the Glacier Bay National Park superintendent 297–2236. V138°24.53' JUI 101° 44.6 NM From C C C C C C C C C C C C C C C C C C C
<ul> <li>RWY 23: Trees.</li> <li>AIRPORT REMARKS: Unattended. Rwy condition not monitored, recommend present on the rwy. Southwest end of rwy beyond thid has soft sand. V processing plant. Commercial ops may require a commercial use authol 907–697–2230). Helicopter ops are prohibited without a permit from AIRPORT MANAGER: 907-784-3295</li> <li>COMMUNICATIONS: CTAF 122.9</li> <li>COMMUNICATIONS: CTAF 122.9</li> <li>COMMUNICATIONS: CTAF 122.9</li> <li>COMMUNICATIONS: CAF 123.9</li> <li>COMMUNICATIONS: C</li></ul>	Windsock 0.2 miles north on the riverbank at t         prization (ctc Glacier Bay National Park         the Glacier Bay National Park superintendent.         -297-2236.         101° 44.6 NM From C C C C C C C C C C C C C C C C C C C
<ul> <li>RWY 23: Trees.</li> <li>AIRPORT REMARKS: Unattended. Rwy condition not monitored, recommend present on the rwy. Southwest end of rwy beyond thild has soft sand. W processing plant. Commercial ops may require a commercial use author 907–697–2230). Helicopter ops are prohibited without a permit from AIRPORT MANAGER: 907-784-3295</li> <li>COMMUNICATIONS: CTAF 122.9</li> <li>COMMUNICATIONS: CTAF 122.9</li> <li>COMM/NAV/WEATHER REMARKS: For a toll free call to Juneau FSS dial 1–866-</li> <li>EAST ALSEK RIVER (AK76) 49 SE UTC-9(–8DT) N59°07.58' W 39 NOTAM FILE YAK</li> <li>RWY 02–20: 1500X10 (TURF) 0.3% up N RWY 02: Trees.</li> <li>AIRPORT REMARKS: Unattended. Turf rwy soft and wet in spring and after heavy rains. Rwy safety area ground rises and falls over 12", maintain centerline control. Rwy used by bears and ATV. Cabin at airstrip maintained by US Forest Svc. Width of path cut through trees 80'. Windsock in fair condition, mounted on spruce tree and partially obscured by other trees.</li> <li>AIRPORT MANAGER: 907-784-3295</li> </ul>	Vindsock 0.2 miles north on the riverbank at t prization (ctc Glacier Bay National Park the Glacier Bay National Park superintendent. -297–2236. V138°24.53 'JU 101° 44.6 NM From CCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCC
RWY 23: Trees. AIRPORT REMARKS: Unattended. Rwy condition not monitored, recommend present on the rwy. Southwest end of rwy beyond thild has soft sand. V processing plant. Commercial ops may require a commercial use author 907–697–2230). Helicopter ops are prohibited without a permit from AIRPORT MANAGER: 907-784-3295 COMMUNICATIONS: CTAF 122.9 COMM/NAV/WEATHER REMARKS: For a toll free call to Juneau FSS dial 1–866– EAST ALSEK RIVER (AK76) 49 SE UTC–9(–8DT) N59°07.58' W 39 NOTAM FILE YAK RWY 02–20: 1500X10 (TURF) 0.3% up N RWY 02: Trees. RWY 02: Trees. AIRPORT REMARKS: Unattended. Turf rwy soft and wet in spring and after heavy rains. Rwy safety area ground rises and falls over 12", maintain centerline control. Rwy used by bears and ATV. Cabin at airstrip maintained by US Forest Svc. Width of path cut through trees 80'. Windsock in fair condition, mounted on spruce tree and partially obscured by other trees. AIRPORT MANAGER: 907-784-3295 COMMUNICATIONS: CTAF 122.9	Windsock 0.2 miles north on the riverbank at t         prization (ctc Glacier Bay National Park         the Glacier Bay National Park superintendent.         -297-2236.         101° 44.6 NM From C C C C C C C C C C C C C C C C C C C
<ul> <li>RWY 23: Trees.</li> <li>AIRPORT REMARKS: Unattended. Rwy condition not monitored, recommend present on the rwy. Southwest end of rwy beyond thid has soft sand. V processing plant. Commercial ops may require a commercial use autho 907–697–2230). Helicopter ops are prohibited without a permit from AIRPORT MANAGER: 907-784-3295</li> <li>COMMUNICATIONS: CTAF 122.9</li> <li>COMMUNETHER REMARKS: For a toll free call to Juneau FSS dial 1–866-</li> <li>EAST ALSEK RIVER (AK76) 49 SE UTC-9(-8DT) N59°07.58 ' W 39 NOTAM FILE YAK</li> <li>RWY 02-20: 1500X10 (TURF) 0.3% up N RWY 02-30: 1500X10 (TURF) 0.3% up N RWY 02- Trees.</li> <li>AIRPORT REMARKS: Unattended. Turf rwy soft and wet in spring and after heavy rains. Rwy safety area ground rises and falls over 12°, maintain centerline control. Rwy used by bears and ATV. Cabin at airstrip maintained by US Forest Svc. Width of path cut through trees 80'. Windsock in fair condition, mounted on spruce tree and partially obscured by other trees.</li> <li>AIRPORT MANAGER: 907-784-3295</li> <li>COMMUNICATIONS: CTAF 122.9</li> <li>RADIO AIDS TO NAVIGATION: NOTAM FILE YAK.</li> </ul>	Vindsock 0.2 miles north on the riverbank at t rization (ctc Glacier Bay National Park the Glacier Bay National Park superintendent. 297–2236. V138°24.53 ' JU 101° 44.6 NM From C C C C C C C C C C C C C C C C C C C
<ul> <li>RWY 23: Trees.</li> <li>AIRPORT REMARKS: Unattended. Rwy condition not monitored, recommend present on the rvy. Southwest end of rwy beyond thid has soft sand. V processing plant. Commercial ops may require a commercial use author 907–697–2230). Helicopter ops are prohibited without a permit from AIRPORT MANAGER: 907-784-3295</li> <li>COMMUNICATIONS: CTAF 122.9</li> <li>COMMUNICATIONS: Unattended. Turf rwy soft and wet in spring and after heavy rains. Rwy safety area ground rises and falls over 12°, maintain centerline control. Rwy used by bears and ATV. Cabin at airstrip maintained by US Forest Svc. Width of path cut through trees 80'. Windsock in fair condition, mounted on spruce tree and partially obscured by other trees.</li> <li>AIRPORT MANAGER: 907-784-3295</li> <li>COMMUNICATIONS: CTAF 122.9</li> <li>RADIO AIDS TO NAVIGATION: NOTAM FILE YAK. YAKUTAT (H) (H) VORW/DME 113.3 YAK Chan 80 N59°30.65'</li> </ul>	Vindsock 0.2 miles north on the riverbank at t prization (ctc Glacier Bay National Park the Glacier Bay National Park superintendent. 297–2236. 101° 44.6 NM From $C \subset C $
<ul> <li>RWY 23: Trees.</li> <li>AIRPORT REMARKS: Unattended. Rwy condition not monitored, recommend present on the rwy. Southwest end of rwy beyond thid has soft sand. W processing plant. Commercial ops may require a commercial use authol 907–697–2230). Helicopter ops are prohibited without a permit from AIRPORT MANAGER: 907-784-3295</li> <li>COMMUNICATIONS: CTAF 122.9</li> <li>COMMUNICATIONS: CTAF 122.9</li> <li>COMMUNICATIONS: CTAF 122.9</li> <li>COMMUNICATIONS: CAF 122.9</li> <li>COMMUNICATIONS: TRESS (AK76) 49 SE UTC-9(-8DT) N59°07.58 'W 39 NOTAM FILE YAK</li> <li>RWY 02-20: 1500X10 (TURF) 0.3% up N RWY 02: Trees.</li> <li>RWY 02: Trees.</li> <li>AIRPORT REMARKS: Unattended. Turf rwy soft and wet in spring and after heavy rains. Rwy safety area ground rises and falls over 12", maintain centerline control. Rwy used by bears and ATV. Cabin at airstrip maintained by US Forest Svc. Width of path cut through trees 80'. Windsock in fair condition, mounted on spruce tree and partially obscured by other trees.</li> <li>AIRPORT MANAGER: 907-784-3295</li> <li>COMMUNICATIONS: CTAF 122.9</li> <li>RADIO AIDS TO NAVIGATION: NOTAM FILE YAK.</li> <li>YAUTAT (H) (H) VORW/DME 113.3 YAK Chan 80 N59°30.65' W139°38.89' 101° 44.6 NM to fid. 41/20E.</li> </ul>	Windsock 0.2 miles north on the riverbank at t         prization (ctc Glacier Bay National Park the Glacier Bay National Park superintendent.         -297-2236.         V138°24.53'         JUI         101° 44.6 NM From       C C C C C C C C C C C C C C C C C C C
<ul> <li>RWY 23: Trees.</li> <li>AIRPORT REMARKS: Unattended. Rwy condition not monitored, recommend present on the rwy. Southwest end of rwy beyond thild has soft sand. W processing plant. Commercial ops may require a commercial use author 907–697–2230). Helicopter ops are prohibited without a permit from AIRPORT MANAGER: 907-784-3295</li> <li>COMMUNICATIONS: CTAF 122.9</li> <li>COMMUNICATIONS: CTAF 122.9</li> <li>COMM/NAV/WEATHER REMARKS: For a toll free call to Juneau FSS dial 1–866-</li> <li>EAST ALSEK RIVER (AK76) 49 SE UTC-9(-8DT) N59°07.58′ W 39 NOTAM FILE YAK</li> <li>RWY 02-20: 1500X10 (TURF) 0.3% up N RWY 02: Trees.</li> <li>AIRPORT REMARKS: Unattended. Turf rwy soft and wet in spring and after heavy rains. Rwy safety area ground rises and falls over 12°, maintain centerline control. Rwy used by bears and ATV. Cabin at airstrip maintained by US Forest Svc. Width of path cut through trees 80′. Windsock in fair condition, mounted on spruce tree and partially obscured by other trees.</li> <li>AIRPORT MANAGER: 907-784-3295</li> <li>COMMUNICATIONS: CTAF 122.9</li> <li>RADIO AIDS TO NAVIGATION: NOTAM FILE YAK.</li> <li>YAKUTAT (H) (H) VORW/DME 113.3 YAK Chan 80 N59°30.65′ W139°38.89′ 101° 44.6 NM to fid. 41/20E. VOR unusable:</li> </ul>	Windsock 0.2 miles north on the riverbank at t         prization (ctc Glacier Bay National Park the Glacier Bay National Park superintendent.         -297-2236.         V138°24.53'         JUI         101° 44.6 NM From       C C C C C C C C C C C C C C C C C C C
<ul> <li>RWY 23: Trees.</li> <li>AIRPORT REMARKS: Unattended. Rwy condition not monitored, recommend present on the rwy. Southwest end of rwy beyond thid has soft sand. V processing plant. Commercial ops may require a commercial use autho 907–697–2230). Helicopter ops are prohibited without a permit from AIRPORT MANAGER: 907-784-3295</li> <li>COMMUNICATIONS: CTAF 122.9</li> <li>COMMUNICATIONS: CTAF 122.9</li> <li>COMMUNICATIONS: CTAF 122.9</li> <li>COMMUNICATIONS: CTAF 22.9</li> <li>COMMUNICATIONS: CTAF 22.9</li> <li>COMMUNICATIONS: CTAF 122.9</li> <li>COMMUNICATIONS: CTAF 22.9</li> <li>COMMUNICATIONS: CTAF 22.9</li> <li>COMMUNICATIONS: CTAF 22.9</li> <li>COMMUNICATIONS: CTAF 22.9</li> <li>RAIPORT REMARKS: Unattended. Turf rwy soft and wet in spring and after heavy rains. Rwy safety area ground rises and falls over 12°, maintain centerline control. Rwy used by bears and ATV. Cabin at airstrip maintained by US Forest Svc. Width of path cut through trees 80'. Windsock in fair condition, mounted on spruce tree and partially obscured by other trees.</li> <li>AIRPORT MANAGER: 907-784-3295</li> <li>COMMUNICATIONS: CTAF 122.9</li> <li>RADIO AIDS TO NAVIGATION: NOTAM FILE YAK.</li> <li>YAKUTAT (H) (H) YORW/DME 113.3 YAK Chan 80 N59°30.65' W139°38.89' 101° 44.6 NM to fid. 41/20E.</li> <li>YOR unvaable: 124°-261° byd 22 NM blo 10,000'</li> </ul>	Windsock 0.2 miles north on the riverbank at t trization (ctc Glacier Bay National Park the Glacier Bay National Park superintendent. 297–2236. $101^{\circ} 44.6 \text{ NM From}$ C C C C C C C C C C C C C C C C C C C
<ul> <li>RWY 23: Trees.</li> <li>AIRPORT REMARKS: Unattended. Rwy condition not monitored, recommend present on the rwy. Southwest end of rwy beyond thild has soft sand. W processing plant. Commercial ops may require a commercial use author 907–697–2230). Helicopter ops are prohibited without a permit from AIRPORT MANAGER: 907-784-3295</li> <li>COMMUNICATIONS: CTAF 122.9</li> <li>COMMUNICATIONS: CTAF 2000 (TURF) 0.3% up N RWY 02-20: 1500X10 (TURF) 0.3% up N RWY 02-30: 500X10 (TURF) 0.3% up N RWY 02-30: 500X10, (TURF) 0.3% UP N RWY 20: Trees.</li> <li>AIRPORT MANAGER: 907-784-3295</li> <li>COMMUNICATIONS: CTAF 122.9</li> <li>RADIO AIDS TO NAVIGATION: NOTAM FILE YAK.</li> <li>YAUTAT (H) (H) VORW/DME 113.3 YAK Chan 80 N59°30.65' W139°38.89' 101° 44.6 NM to fid. 41/20E.</li> <li>VOR unusable: 124°-261° byd 22 NM bio 10,000' DME unusable:</li> </ul>	Windsock 0.2 miles north on the riverbank at t trization (ctc Glacier Bay National Park the Glacier Bay National Park superintendent. 297–2236. 101° 44.6 NM From $\bigcirc \bigcirc \bigcirc$
<ul> <li>RWY 23: Trees.</li> <li>AIRPORT REMARKS: Unattended. Rwy condition not monitored, recommend present on the rwy. Southwest end of rwy beyond thid has soft sand. V processing plant. Commercial ops may require a commercial use autho 907–697–2230). Helicopter ops are prohibited without a permit from AIRPORT MANAGER: 907-784-3295</li> <li>COMMUNICATIONS: CTAF 122.9</li> <li>COMMUNICATIONS: CTAF 122.9</li> <li>COMMUNICATIONS: CTAF 122.9</li> <li>COMMUNICATIONS: CTAF 22.9</li> <li>COMMUNICATIONS: CTAF 22.9</li> <li>COMMUNICATIONS: CTAF 122.9</li> <li>COMMUNICATIONS: CTAF 22.9</li> <li>COMMUNICATIONS: CTAF 22.9</li> <li>COMMUNICATIONS: CTAF 22.9</li> <li>COMMUNICATIONS: CTAF 22.9</li> <li>RAIPORT REMARKS: Unattended. Turf rwy soft and wet in spring and after heavy rains. Rwy safety area ground rises and falls over 12°, maintain centerline control. Rwy used by bears and ATV. Cabin at airstrip maintained by US Forest Svc. Width of path cut through trees 80'. Windsock in fair condition, mounted on spruce tree and partially obscured by other trees.</li> <li>AIRPORT MANAGER: 907-784-3295</li> <li>COMMUNICATIONS: CTAF 122.9</li> <li>RADIO AIDS TO NAVIGATION: NOTAM FILE YAK.</li> <li>YAKUTAT (H) (H) YORW/DME 113.3 YAK Chan 80 N59°30.65' W139°38.89' 101° 44.6 NM to fid. 41/20E.</li> <li>YOR unvaable: 124°-261° byd 22 NM blo 10,000'</li> </ul>	Vindsock 0.2 miles north on the riverbank at th rization (ctc Glacier Bay National Park the Glacier Bay National Park superintendent. -297–2236. V138°24.53' JUN $101^{\circ}$ 44.6 NM From $C$