

VALDEZ

ROBE LAKE SPB (L93) 6 W UTC-9(-8DT) N61°05.23' W146°08.64'

ANCHORAGE

39 NOTAM FILE JNU

WATERWAY E-W: 4000X200 (WATER)

WATERWAY N-S: 2000X200 (WATER)

SERVICE: FUEL JET A

SEAPLANE REMARKS: Unattended. Caution: beaching area used by boats and swimmers; Dock NA. Steel bars protruding from water near the shore line.

AIRPORT MANAGER: 907-831-1386

COMMUNICATIONS: CTAF 122.9

COMM/NAV/WEATHER REMARKS: For a toll free call to Juneau FSS dial 1-866-297-2236.

THOMPSON PASS (K55) 17 E UTC-9(-8DT) N61°10.64' W145°41.31'

ANCHORAGE

2080 NOTAM FILE JNU

RWY 05-23: 2530X9 (TURF-GRVL)

RWY 05: Brush.

RWY 23: Brush.

AIRPORT REMARKS: Unattended. All ops PPR—amgr. Rwy 05-23 unsafe for Indg, tkof or TGL due to debris on rwy - amgr. Rwy cond unmnt: rcmd visual insp prior to use. High trrn all quads. Exp turbulent wind. Unctld vehicle t/c on rwy. Rwy end 23: Pwr line crosses hill on apch end. Rwy end 05: first 300 ft soft & rutted. 1 ft grass & brush first 1200 ft; remainder 10 ft brush. Rwy 05-23: E side 9 ft unusbl; rmng overgrown with 4 ft brush. Rwy 05-23: east half of rwy overgrown 10 ft brush; strip 10 x 2270 ft unusable. West half of rwy loose gravel and small brush to 6 in. Rwy 05-23 soft aft rain, rises slightly at each end.

AIRPORT MANAGER: 907-269-8508

COMMUNICATIONS: CTAF 122.9

RCO 122.55 (JUNEAU RADIO)

RADIO AIDS TO NAVIGATION: NOTAM FILE VDZ.

MINERAL CREEK NDB (MHW) 524 MNL N61°07.45'

W146°21.13' 061° 19.6 NM to fld. 21/19E.

NDB unusable:

320°-010° byd 15 NM

COMM/NAV/WEATHER REMARKS: For a toll free call to Juneau FSS dial 1-866-297-2236.

