	a == (
ALSEK RIVER (A57) 44 SE UTC-9(-8DT) N59°11.95′ W138°26	6.75´ J
53 NOTAM FILE JNU	
RWY 07-25: 1860X12 (TURF) RWY 07: Tree.	096° 41.4 NM From C C C C C
	Yakutat "YAK" VOR/DME
RWY 25: Tree.	0 00 00 00 00 00 0 0
AIRPORT REMARKS: Unattended. Wildlife invof rwy. Erratic winds off mountain range east of rwy. Rwy uneven on both sides with several dips over 12".	
Maintain centerline ctl during ldg and tkf. Gully on thld Rwy 07,	
recommend touch down in front of USFS cabin. Rwy 07–25 soft and wet	
during Spring and after heavy rains. Rwy 07–25 NSTD markings, thld	
marked with yellow plastic pipes.	00 000 00000 000 000
AIRPORT MANAGER: 907-784-3359	0,00,00,0,0,0,0,00,00
COMMUNICATIONS: CTAF 122.9	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
RADIO AIDS TO NAVIGATION: NOTAM FILE YAK.	N Excercises and the second se
YAKUTAT (H) (H) VORW/DME 113.3 YAK Chan 80 N59°30.65'	000 - 1860 X 12 00 00
W139°38.89′ 096° 41.4 NM to fld. 41/20E.	
VOR unusable:	
124°-261° byd 22 NM blo 10,000'	
DME unusable:	6
124°-261° byd 22 NM blo 10,000′	00 200 0 20 00 00
COMM/NAV/WEATHER REMARKS: For a toll free call to Juneau FSS dial 1–866–297–2236.	65 555 555 555 555 5 5 5 5 5 5 5 5 5 5
1-000-297-2230.	
DRY BAY (3AK) 44 SE UTC-9(-8DT) N59°09.86´W138°29.33´	·
DRY BAY (3AK) 44 SE UTC-9(-8DT) N59°09.86' W138°29.33' 33 NOTAM FILE JNU	
RWY 05–23: 3600X170 (GRVL)	
RWY 05: Trees.	
RWY 23: Trees. AIRPORT REMARKS: Unattended. Rwy condition not monitored, recommend w present on the rwy. Southwest end of rwy beyond thId has soft sand. W processing plant. Commercial ops may require a commercial use autho	Vindsock 0.2 miles north on the riverbank a
AIRPORT REMARKS: Unattended. Rwy condition not monitored, recommend v present on the rwy. Southwest end of rwy beyond thild has soft sand. W	Vindsock 0.2 miles north on the riverbank a prization (ctc Glacier Bay National Park
AIRPORT REMARKS: Unattended. Rwy condition not monitored, recommend w present on the rwy. Southwest end of rwy beyond thid has soft sand. W processing plant. Commercial ops may require a commercial use autho 907–697–2230). Helicopter ops are prohibited without a permit from AIRPORT MANAGER: 907-784-3295	Vindsock 0.2 miles north on the riverbank a vization (ctc Glacier Bay National Park the Glacier Bay National Park superintender
AIRPORT REMARKS: Unattended. Rwy condition not monitored, recommend w present on the rwy. Southwest end of rwy beyond thid has soft sand. W processing plant. Commercial ops may require a commercial use autho 907–697–2230). Helicopter ops are prohibited without a permit from AIRPORT MANAGER: 907-784-3295 COMMUNICATIONS: CTAF 122.9 COMM/NAV/WEATHER REMARKS: For a toll free call to Juneau FSS dial 1–866–	Vindsock 0.2 miles north on the riverbank a rization (ctc Glacier Bay National Park the Glacier Bay National Park superintende 297–2236.
AIRPORT REMARKS: Unattended. Rwy condition not monitored, recommend of present on the rwy. Southwest end of rwy beyond thild has soft sand. We processing plant. Commercial ops may require a commercial use author 907–697–2230). Helicopter ops are prohibited without a permit from AIRPORT MANAGER: 907-784-3295 COMMUNICATIONS: CTAF 122.9 COMM/NAV/WEATHER REMARKS: For a toll free call to Juneau FSS dial 1–866–	Vindsock 0.2 miles north on the riverbank a rization (ctc Glacier Bay National Park the Glacier Bay National Park superintende 297–2236.
AIRPORT REMARKS: Unattended. Rwy condition not monitored, recommend of present on the rwy. Southwest end of rwy beyond thild has soft sand. We processing plant. Commercial ops may require a commercial use author 907–697–2230). Helicopter ops are prohibited without a permit from AIRPORT MANAGER: 907-784-3295 COMMUNICATIONS: CTAF 122.9 COMM/NAV/WEATHER REMARKS: For a toll free call to Juneau FSS dial 1–866– EAST ALSEK RIVER (AK76) 49 SE UTC–9(–8DT) N59°07.58' W 39 NOTAM FILE YAK	Vindsock 0.2 miles north on the riverbank a rization (ctc Glacier Bay National Park the Glacier Bay National Park superintende 297–2236.
 AIRPORT REMARKS: Unattended. Rwy condition not monitored, recommend we present on the rwy. Southwest end of rwy beyond thild has soft sand. We processing plant. Commercial ops may require a commercial use author 907–697–2230). Helicopter ops are prohibited without a permit from AIRPORT MANAGER. 907-784-3295 COMMUNICATIONS: CTAF 122.9 COMMUNICATIONS: CTAF 122.9	Vindsock 0.2 miles north on the riverbank a rization (ctc Glacier Bay National Park the Glacier Bay National Park superintende 297–2236.
AIRPORT REMARKS: Unattended. Rwy condition not monitored, recommend we present on the rwy. Southwest end of rwy beyond thild has soft sand. We processing plant. Commercial ops may require a commercial use author 907–697–2230). Helicopter ops are prohibited without a permit from AIRPORT MANAGER: 907-784-3295 COMMUNICATIONS: CTAF 122.9 COMMUNICATIONS: CTAF 122.9 COMMUNICA	Vindsock 0.2 miles north on the riverbank a rization (ctc Glacier Bay National Park the Glacier Bay National Park superintende 297–2236. /138°24.53´ 101° 44.6 NM From CCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCC
 AIRPORT REMARKS: Unattended. Rwy condition not monitored, recommend we present on the rwy. Southwest end of rwy beyond thild has soft sand. We processing plant. Commercial ops may require a commercial use author 907–697–2230). Helicopter ops are prohibited without a permit from AIRPORT MANAGER. 907-784-3295 COMMUNICATIONS: CTAF 122.9 COMMUNICATIONS: CTAF 122.9	Vindsock 0.2 miles north on the riverbank a rization (ctc Glacier Bay National Park the Glacier Bay National Park superintende 297–2236. //138°24.53´ 101° 44.6 NM From CCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCC
 AIRPORT REMARKS: Unattended. Rwy condition not monitored, recommend we present on the rwy. Southwest end of rwy beyond thild has soft sand. We processing plant. Commercial ops may require a commercial use author 907–697–2230). Helicopter ops are prohibited without a permit from AIRPORT MANAGER: 907-784-3295 COMMUNICATIONS: CTAF 122.9 COMMUNICATIONS: CTAF 122.9	Vindsock 0.2 miles north on the riverbank a rization (ctc Glacier Bay National Park the Glacier Bay National Park superintende 297–2236. //138°24.53´ 101° 44.6 NM From CCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCC
 AIRPORT REMARKS: Unattended. Rwy condition not monitored, recommend of present on the rwy. Southwest end of rwy beyond thid has soft sand. W processing plant. Commercial ops may require a commercial use autho 907–697–2230). Helicopter ops are prohibited without a permit from AIRPORT MANAGER. 907-784-3295 COMMUNICATIONS: CTAF 122.9 COMMUNICATIONS: CTAF 122.9	Vindsock 0.2 miles north on the riverbank a rization (ctc Glacier Bay National Park the Glacier Bay National Park superintende 297–2236. 101° 44.6 NM From CCCCCCC Yokutat "YAK" VOR/DME CCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCC
 AIRPORT REMARKS: Unattended. Rwy condition not monitored, recommend w present on the rwy. Southwest end of rwy beyond thid has soft sand. W processing plant. Commercial ops may require a commercial use autho 907–697–2230). Helicopter ops are prohibited without a permit from AIRPORT MANAGER: 907-784-3295 COMMUNICATIONS: CTAF 122.9 COMMUNICATIONS: CTAF 122.9	Vindsock 0.2 miles north on the riverbank a prization (ctc Glacier Bay National Park the Glacier Bay National Park superintender 297–2236. 101° 44.6 NM From $CCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCC$
 AIRPORT REMARKS: Unattended. Rwy condition not monitored, recommend of present on the rwy. Southwest end of rwy beyond thid has soft sand. W processing plant. Commercial ops may require a commercial use autho 907–697–2230). Helicopter ops are prohibited without a permit from AIRPORT MANAGER. 907-784-3295 COMMUNICATIONS: CTAF 122.9 COMMUNICATIONS: CTAF 122.9	Vindsock 0.2 miles north on the riverbank a prization (ctc Glacier Bay National Park the Glacier Bay National Park superintender 297–2236. 101° 44.6 NM From $CCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCC$
 AIRPORT REMARKS: Unattended. Rwy condition not monitored, recommend we present on the rwy. Southwest end of rwy beyond thild has soft sand. We processing plant. Commercial ops may require a commercial use author 907–697–2230). Helicopter ops are prohibited without a permit from AIRPORT MANAGER: 907-784-3295 COMMUNICATIONS: CTAF 122.9 RWY 02: Trees. RWY 02: Trees. RWY 02: Trees. RWY 02: Trees. RWP 02: Trees.	Vindsock 0.2 miles north on the riverbank a rization (ctc Glacier Bay National Park the Glacier Bay National Park superintende 297–2236. 101° 44.6 NM From CCCCC CCC Yokutat "YAK" VOR/DME CCCCC CCCCCCCCCCCCCCCCCCCCCCCCCCCCCCC
 AIRPORT REMARKS: Unattended. Rwy condition not monitored, recommend we present on the rwy. Southwest end of rwy beyond thild has soft sand. We processing plant. Commercial ops may require a commercial use author 907–697–2230). Helicopter ops are prohibited without a permit from AIRPORT MANAGER: 907-784-3295 COMMUNICATIONS: CTAF 122.9 RWY 02: Trees. RWY 02: Trees. AIRPORT REMARKS: Unattended. Turf rwy soft and wet in spring and after heavy rains. Rwy safety area ground rises and falls over 12", maintain centerline control. Rwy used by bears and ATV. Cabin at airstrip maintained by US Forest Svc. Width of path cut through trees 80'. Windsock in fair condition, mounted on spruce tree and partially 	Vindsock 0.2 miles north on the riverbank a prization (ctc Glacier Bay National Park the Glacier Bay National Park superintender 297–2236. 101° 44.6 NM From $\begin{array}{c} C & C & C \\ C & C & C \\ Yokutat "YAK" VOR/DME & C & C \\ C & C & C & C \\ C & C & C & C$
 AIRPORT REMARKS: Unattended. Rwy condition not monitored, recommend of present on the rwy. Southwest end of rwy beyond thild has soft sand. W processing plant. Commercial ops may require a commercial use autho 907–697–2230). Helicopter ops are prohibited without a permit from AIRPORT MANAGER: 907-784-3295 COMMUNICATIONS: CTAF 122.9 COMMUNICATIONS: CTAF 122.9	Vindsock 0.2 miles north on the riverbank a rization (ctc Glacier Bay National Park the Glacier Bay National Park superintender 297–2236. 101° 44.6 NM From CCCCCCC Yokutat "YAK" VOR/DME CCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCC
 AIRPORT REMARKS: Unattended. Rwy condition not monitored, recommend of present on the rwy. Southwest end of rwy beyond thild has soft sand. We processing plant. Commercial ops may require a commercial use author 907–697–2230). Helicopter ops are prohibited without a permit from AIRPORT MANAGER. 907-784-3295 COMMUNICATIONS: CTAF 122.9 COMMUNAV/WEATHER REMARKS: For a toll free call to Juneau FSS dial 1–866– EAST ALSEK RIVER (AK76) 49 SE UTC–9(–8DT) N59°07.58' W 39 NOTAM FILE YAK RWY 02-20: 1500X10 (TURF) 0.3% up N RWY 02: Trees. RWY 02: Trees. AIRPORT REMARKS: Unattended. Turf rwy soft and wet in spring and after heavy rains. Rwy safety area ground rises and falls over 12", maintain centerline control. Rwy used by bears and ATV. Cabin at airstrip maintained by US Forest Svc. Width of path cut through trees 80'. Windsock in fair condition, mounted on spruce tree and partially obscured by other trees. AIRPORT MANAGER: 907-784-3295 	Vindsock 0.2 miles north on the riverbank a prization (ctc Glacier Bay National Park the Glacier Bay National Park superintender 297–2236. 101° 44.6 NM From $\begin{array}{c} C & C & C \\ C & C & C \\ Yokutat "YAK" VOR/DME & C & C \\ C & C & C & C \\ C & C & C & C$
 AIRPORT REMARKS: Unattended. Rwy condition not monitored, recommend w present on the rwy. Southwest end of rwy beyond thild has soft sand. W processing plant. Commercial ops may require a commercial use autho 907–697–2230). Helicopter ops are prohibited without a permit from AIRPORT MANAGER. 907-784-3295 COMMUNICATIONS: CTAF 122.9 	Vindsock 0.2 miles north on the riverbank a rization (ctc Glacier Bay National Park the Glacier Bay National Park superintende 297–2236. /138°24.53′ 101° 44.6 NM From CCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCC
 AIRPORT REMARKS: Unattended. Rwy condition not monitored, recommend w present on the rwy. Southwest end of rwy beyond thild has soft sand. W processing plant. Commercial ops may require a commercial use autho 907–697–2230). Helicopter ops are prohibited without a permit from AIRPORT MANAGER: 907-784-3295 COMMUNICATIONS: CTAF 122.9 COMM/NAV/WEATHER REMARKS: For a toll free call to Juneau FSS dial 1–866– EAST ALSEK RIVER (AK76) 49 SE UTC–9(–8DT) N59°07.58' W 39 NOTAM FILE YAK RWY 02-20: 1500X10 (TURF) 0.3% up N RWY 02: Trees. RWY 20: Trees. RWP 20: Trees. AIRPORT REMARKS: Unattended. Turf rwy soft and wet in spring and after heavy rains. Rwy safety area ground rises and falls over 12", maintain centerline control. Rwy used by bears and ATV. Cabin at airstrip maintained by US Forest Svc. Width of path cut through trees 80'. Windsock in fair condition, mounted on spruce tree and partially obscured by other trees. AIRPORT MANAGER: 907-784-3295 COMMUNICATIONS: CTAF 122.9 RADIO AIDS TO NAVIGATION: NOTAM FILE YAK. 	Vindsock 0.2 miles north on the riverbank a prization (ctc Glacier Bay National Park the Glacier Bay National Park superintende 297–2236. 101° 44.6 NM From $\begin{array}{c} \alpha & \alpha $
 AIRPORT REMARKS: Unattended. Rwy condition not monitored, recommend w present on the rwy. Southwest end of rwy beyond thild has soft sand. W processing plant. Commercial ops may require a commercial use autho 907–697–2230). Helicopter ops are prohibited without a permit from AIRPORT MANAGER. 907-784-3295 COMMUNICATIONS: CTAF 122.9 RWY 02-20: 1500X10 (TURF) 0.3% up N RWY 02: Trees. AIRPORT REMARKS: Unattended. Turf rwy soft and wet in spring and after heavy rains. Rwy safety area ground rises and falls over 12", maintain centerline control. Rwy used by bears and ATV. Cabin at airstrip maintained by US Forest Svc. Width of path cut through trees 80'. Windsock in fair condition, mounted on spruce tree and partially obscured by other trees. AIRPORT MANAGER: 907-784-3295 COMMUNICATIONS: CTAF 122.9 RADIO AIDS TO NAVIGATION: NOTAM FILE YAK. YAKUTAT (H) (H) VORW/DME 113.3 YAK Chan 80 N59°30.65' W139°38.89' 101° 44.6 NM to fid. 41/20E. VOR unusable: 	Vindsock 0.2 miles north on the riverbank a rization (ctc Glacier Bay National Park the Glacier Bay National Park superintende 297–2236. /138°24.53′ 101° 44.6 NM From CCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCC
 AIRPORT REMARKS: Unattended. Rwy condition not monitored, recommend w present on the rwy. Southwest end of rwy beyond thild has soft sand. W processing plant. Commercial ops may require a commercial use autho 907–697–2230). Helicopter ops are prohibited without a permit from AIRPORT MANAGER. 907-784-3295 COMMUNICATIONS: CTAF 122.9 RWY 02: Trees. RWY 02: Trees. RWY 02: Trees. RWY 02: Trees. RWP 02: Trees. RWP 02: Trees. RWP 02: Trees. AIRPORT REMARKS: Unattended. Turf rwy soft and wet in spring and after heavy rains. Rwy safety area ground rises and falls over 12", maintain centerline control. Rwy used by bears and ATV. Cabin at airstrip maintained by US Forest Svc. Width of path cut through trees 80'. Windsock in fair condition, mounted on spruce tree and partially obscured by other trees. AIRPORT MANAGER: 907-784-3295 COMMUNICATIONS: CTAF 122.9 RADIO AIDS TO NAVIGATION: NOTAM FILE YAK. YAKUTAT (H) (H) VORW(DME 113.3 YAK Chan 80 N59°30.65' W139°38.89' 101° 44.6 NM to fid. 41/20E. VOR unusable: 124°-261° byd 22 NM bio 10,000' 	Vindsock 0.2 miles north on the riverbank a rization (ctc Glacier Bay National Park the Glacier Bay National Park superintender 297–2236. 101° 44.6 NM From $\begin{array}{c} \alpha & \alpha & \alpha & \alpha \\ \gamma & \alpha \\ \end{array}$
 AIRPORT REMARKS: Unattended. Rwy condition not monitored, recommend of present on the rwy. Southwest end of rwy beyond thild has soft sand. W processing plant. Commercial ops may require a commercial use autho 907–697–2230). Helicopter ops are prohibited without a permit from AIRPORT MANAGER. 907-784-3295 COMMUNICATIONS: CTAF 122.9 CONTAM FILE YAK RWY 02-20: 1500X10 (TURF) 0.3% up N RWY 02-Trees. RWY 02: Trees. AIRPORT REMARKS: Unattended. Turf rwy soft and wet in spring and after heavy rains. Rwy safety area ground rises and falls over 12", maintain centerline control. Rwy used by bears and ATV. Cabin at airstrip maintained by US Forest Svc. Width of path cut through trees 80'. Windsock in fair condition, mounted on spruce tree and partially obscured by other trees. AIRPORT MANAGER: 907-784-3295 COMMUNICATIONS: CTAF 122.9 RADIO AIDS TO NAVIGATION: NOTAM FILE YAK. YAKUTAT (H) (H) VORW/DME 113.3 YAK Chan 80 N59°30.65' W139°38.89' 101° 44.6 NM to fid. 41/20E. VOR unusable: 124°-261° byd 22 NM blo 10,000' DME unusable: 	Vindsock 0.2 miles north on the riverbank a rization (ctc Glacier Bay National Park the Glacier Bay National Park superintender 297–2236. 101° 44.6 NM From $\bigcirc \bigcirc \bigcirc$
 AIRPORT REMARKS: Unattended. Rwy condition not monitored, recommend w present on the rwy. Southwest end of rwy beyond thild has soft sand. W processing plant. Commercial ops may require a commercial use autho 907–697–2230). Helicopter ops are prohibited without a permit from AIRPORT MANAGER: 907-784-3295 COMMUNICATIONS: CTAF 122.9 RWY 02: Trees. RWY 02: Trees. RWY 02: Trees. RWY 20: Trees. RWY 20: Trees. RWP 02: Trees. RWP 20: Trees. RWP 20: Trees. AIRPORT REMARKS: Unattended. Turf rwy soft and wet in spring and after heavy rains. Rwy safety area ground rises and falls over 12", maintain centerline control. Rwy used by bears and ATV. Cabin at airstrip maintained by US Forest Svc. Width of path cut through trees 80'. Windsock in fair condition, mounted on spruce tree and partially obscured by other trees. AIRPORT MANAGER: 907-784-3295 COMMUNICATIONS: CTAF 122.9 RADIO AIDS TO NAVIGATION: NOTAM FILE YAK. YAKUTAT (H) (H) VORW/DME 113.3 YAK Chan 80 N59°30.65' W139°38.89' 101° 44.6 NM to fid. 41/20E. VOR unusable: 124°-261° byd 22 NM bio 10,000' 	Vindsock 0.2 miles north on the riverbank a rization (ctc Glacier Bay National Park the Glacier Bay National Park superintende 297–2236. 101° 44.6 NM From $\begin{array}{c} \alpha & \alpha & \alpha & \alpha & \alpha \\ \alpha & \alpha & \alpha & \alpha & \alpha &$