## ALASKA

YES BAY LODGE SPB (78K) KETCHIKAN 0 N UTC-9(-8DT) N55°54.98' W131°48.07' 00 NOTAM FILE KTN WATERWAY E-W: 5000X2000 (WATER) SEAPLANE REMARKS: Summer ops, boats tied at float. Stream current acft tax. CTN: Logs and debris in water; reef and islands middle of inlet AIRPORT MANAGER: 907-225-7906 COMMUNICATIONS: CTAF 122.9 COMM/NAV/WEATHER REMARKS: For a LC to Ketchikan FSS dial 225-9481. For a LC to Juneau FSS dial 789-7380. YUKON CHARLEY RIVERS COAL CREEK (L2Ø) 1 W UTC-9(-8DT) N65°18.69' W143°08.05' DAWSON 867 NOTAM FILE FAI 1-41 RWY 01-19: 3900X80 (GRVI) 0.3% up S

RWY 19: Road. AIRPORT REMARKS: Unattended. Rwy 01–19 not maintained during winter and early spring. Rwy condition not monitored. Recommend visual inspection prior to using. Rwy 01–19 sfc very rough, rocks up to 6 inch. Rwy 01–19 is a dredged creek bottom sloping uphill north to south. 8 ft high dredge tailings on both sides full length of Rwy 01–19. Rwy 01–19 subject to erratic winds. Rwy located in valley. Rapidly rising terrain to the west and east. Watch for vehicles and pedestrians east edge of Rwy 01–19. Rwy 01–19 thld marked with cones and damaged reflective panels. Limited acft parking along west side near south end of Rwy 01–19. Large rocks in ramp and parking area, up to 18 inches. AIRPORT MANAGER: 907-455-0646 COMMUNICATIONS: CTAF 122.8 SUAIS 125.3 126.3 (1–800–758–8723).

COMM/NAV/WEATHER REMARKS: For a toll free call to Fairbanks FSS dial 1-866-248-6516.

YUKON RIVER BRIDGE N66°00.55′ W149°48.52′ RC0 122.15 (FAIRBANKS RADIO)

RWY 01: Road.

FAIRBANKS L—4j