

## VALDEZ

**ROBE LAKE SPB** (L93) 6 W UTC-9(-8DT) N61°05.23' W146°08.64'

ANCHORAGE

39 NOTAM FILE JNU

**WATERWAY E-W:** 4000X200 (WATER)

**WATERWAY N-S:** 2000X200 (WATER)

**SERVICE:** FUEL JET A

**SEAPLANE REMARKS:** Unattended. Caution: beaching area used by boats and swimmers; Dock NA. Steel bars protruding from water near the shore line.

**AIRPORT MANAGER:** 907-831-1386

**COMMUNICATIONS:** CTAF 122.9

**COMM/NAV/WEATHER REMARKS:** For a toll free call to Juneau FSS dial 1-866-297-2236.

**THOMPSON PASS** (K55) 17 E UTC-9(-8DT) N61°10.64' W145°41.31'

ANCHORAGE

2080 NOTAM FILE JNU

**RWY 05-23:** 2530X9 (TURF-GRVL)

**RWY 05:** Brush.

**RWY 23:** Brush.

**AIRPORT REMARKS:** Unattended. All ops PPR—amgr. Rwy 05-23 unsafe for landings, takeoffs or TGL due to debris on rwy—amgr. Rwy condition unmonitored; recommend visual inspection prior to use. High terrain all quadrants. Expect turbulent wind. Uncontrolled vehicle traffic on rwy. Rwy end 23: Power line crosses hill on approach end. Rwy end 05: first 300 ft soft & rutted. 1 ft grass & brush first 1200 ft; remainder 10 ft brush. Rwy 05-23: East side 9 ft unusable; remaining overgrown with 4 ft brush. Rwy 05-23: east half of rwy overgrown 10 ft brush; strip 10 x 2270 ft unusable. West half of rwy loose gravel and small brush to 6 in. Rwy 05-23 soft after rain, rises slightly at each end.

**AIRPORT MANAGER:** 907-269-8508

**COMMUNICATIONS:** CTAF 122.9

**RCO** 122.55 (JUNEAU RADIO)

**RADIO AIDS TO NAVIGATION:** NOTAM FILE VDZ.

**MINERAL CREEK NDB (MHW)** 524 MNL N61°07.45'

W146°21.13' 061° 19.6 NM to fld. 21/19E.

NDB unusable;

320°-010° by 15 NM

**COMM/NAV/WEATHER REMARKS:** For a toll free call to Juneau FSS dial 1-866-297-2236.

