
AI ASKA

Grvl public ramp lctd on NE shore of lake. No public parking avbl. Major power plant repairs avbl. No winter maintenance be alert during Idg/tkf. A buov has been placed aprx 200' from the most southern point of land on the southeast end of the lake. Acft opr are not allowed inside the 200' marker unless taxiing to or from the shore, or taxiing to the acft run-up area. Pilots should be aware of watercraft and recreational activities on the lake. A visual inspection prior to ldg is recommended. Wind indicator avbl at Willow Arpt across the road. Buoys are removed from lake prior to freeze-up and replaced when lake thaws. It is recommended that all acft tkf toward the south, weather conditions permitting. No east/west tkf or ldg are permitted. AIRPORT MANAGER: 907-495-6286

COMMUNICATIONS: CTAF/UNICOM 122.8

COMM/NAV/WEATHER REMARKS: For a toll free call to Kenai ESS dial 1-866-864-1737

WINGSONG ESTATES (See DELTA JUNCTION on page 93)



WOLF LAKE (See PALMER on page 193)

WOODY ISLAND N57°46.49' W152°19.48' NOTAM FILE ADQ. NDB (HW) 394 RWO 241° 5.6 NM to Kodiak. 24/14E. RC0 122.2 (KENAI RADIO)

KODIAK H-1B. 2K. L-2J. 3D

ANCHORAGE