## REPUBLIC

**FERRY CO** (R49) 6 NE UTC–8(–7DT) N48º43.09´ W118º39.39´ **SEATTLE**
2522 B TPA—3322(800) NOTAM FILE SEA **L–13A**

**RWY 17–35:** H3498X60 (ASPH) MIRL
**RWY 17:** Trees. Rgt tfc.
**RWY 35:** PAPI(P2L)—GA 4.0º TCH 40´. Trees.
**SERVICE:** **LGT** ACTVT PAPI Rwy 35; MIRL Rwy 17–35—122.8.
**AIRPORT REMARKS:** Unattended. Suggest ngt ldgs be made on Rwy 35. Rwy 17–35 trees located on unlgtd unmarked mountainous terrain. P–lines NE of Rwy 17 lgtd dusk–dawn. Wildlife invof of rwy.
**AIRPORT MANAGER:** 616 822-0483
**COMMUNICATIONS: CTAF** 122.9
**CLEARANCE DELIVERY PHONE:** For CD ctc Seattle ARTCC at 253-351-3694.
**RADIO AIDS TO NAVIGATION:** NOTAM FILE EPH.
**EPHRATA (VH) (H) VORTACW** 112.6 EPH Chan 73 N47º22.68´ W119º25.44´ 360º 86.2 NM to fld. 1250/21E.
VOR unusable:
010º–014º byd 40 NM
042º–054º byd 40 NM
214º–228º byd 40 NM blo 7,000´
214º–228º byd 52 NM blo 10,000´
214º–228º byd 77 NM
229º–247º byd 40 NM
310º–350º byd 25 NM blo 6,500´
310º–353º byd 40 NM
358º–004º byd 40 NM
TACAN AZIMUTH unusable:
280º–295º byd 25 NM blo 7,000´
310º–350º byd 25 NM blo 6,500´
DME unusable:
280º–295º byd 25 NM blo 7,000´
310º–350º byd 25 NM blo 6,500´




• • • • • • • • • • • • • • • • • •

**HELIPAD H1:** H20X20 (CONC)
**HELIPAD H2:** H20X20 (CONC)