HOODO SEVEN DEPARTURE (RNAV)

(HOODO7.HOODO) 07OCT21

LA PORTE, TEXAS

LA PORTE MUNI (T41)



DEPARTURE ROUTE DESCRIPTION

TAKEOFF RUNWAY 5: Climb on heading 046° to 540, for RADAR vectors to VUH VOR/DME, thence . . . .
TAKEOFF RUNWAY 12: Climb on heading 121° to 540, for RADAR vectors to VUH VOR/DME, thence . . . .
TAKEOFF RUNWAY 23: Climb on heading 226° to 540, for RADAR vectors to VUH VOR/DME, thence . . . .
TAKEOFF RUNWAY 30: Climb on heading 301° to 540, for RADAR vectors to VUH VOR/DME, thence . . . .

. . . . on track 118° to HOODO, then on (transition). Maintain ATC assigned altitude.
Expect filed altitude 10 minutes after departure.

BOWFN TRANSITION (HOODO7.BOWFN)
CFOOD TRANSITION (HOODO7.CFOOD)
HARVEY TRANSITION (HOODO7.HRV)
LEEVILLE TRANSITION (HOODO7.LEV)
SBIRD TRANSITION (HOODO7.SBIRD)

HOODO SEVEN DEPARTURE (RNAV)

(HOODO7.HOODO) 21280

AL-5433 (FAA)

LA PORTE MUNI (T41)

LA PORTE, TEXAS