

26078

ILS RWY 18R (CAT II)
HUNTSVILLE INTL-CARL T JONES FLD (HSV)

ALSF-2



MISSED APPROACH: Climb to 1300 then climbing right turn to 3000 on heading 270° and RQZ R-230 to JUVLO/RQZ 28.7 DME and hold.

MISSED APCH FIX

112.2 RQZ
R-230
Chan 59

JUVLO
RQZ 28.7

HOLD 5000 3000

R-295

ROCKET
112.2 RQZ
Chan 59

(IF/IAF)
HAGUR INT
RQZ 8
RADAR

FEKER INT
RADAR

R-246

LOCALIZER 109.3
I-HSV

WHEELER NATIONAL
WILDLIFE REFUGE

ELEV 629

TDZE 629

MSA RQZ 25 NM

360°

180°

3200

3700

ELEV 629	D	TDZE 629
----------	----------	----------

CATEGORY II ILS - SPECIAL AIRCREW
& AIRCRAFT CERTIFICATION REQUIRED

TDZL/RCLS Rwy 18R and 36L
HIRL Rwy 18L-36R and 18R-36L **L**

HUNTSVILLE INTL-CARL T JONES FLD (HSV)
34°38'N-86°47'W ILS RWY 18R (CAT II)