

RNAV (RNP) Z RWY 28L
JOHN GLENN COLUMBUS INTL (CMH)

MISSED APPROACH:
Climb to 1400 then
climbing left turn to
3000 direct BOUTN
LOM and hold.

GND CON
121.9 348.6

TDZL/RCLS Rwy 10R-28L
HIRL Rwy 10R-28L and 10L-28R

JOHN GLENN COLUMBUS INTL (CMH)
RNAV (RNP) Z RWY 28L