

LOC I-LNK <u>109.9</u>	APP CRS 357°	Rwy Ldg 12901 TDZE 1175 Apt Elev 1219
----------------------------------	------------------------	--

ILS Y or LOC Y RWY 36
LINCOLN (LNK)

DME required. RADAR required for procedure entry at THEWS.

T For inop ALS, increase S-ILS 36 Cat E visibility to RVR 4000,
A S-LOC 36 Cat E visibility to 1 $\frac{3}{8}$ SM. DME from LNK VORTAC.
DME use requires simultaneous reception of I-LNK and LNK DME.
*RVR 1800 authorized with use of FD or AP or HUD to DA.

MALSR

MISSED APPROACH: Climb to 1700 then climbing right turn to 3100 direct LNK VORTAC and hold, continue climb-in-hold to 3100.

ATIS 118.05 290.9	OMAHA APP CON 124.0 270.3	LINCOLN TOWER★ 118.5 (CTAF) 253.5	GND CON 121.9 275.8	UNICOM 122.95
----------------------	------------------------------	--------------------------------------	------------------------	------------------

