

ILS or LOC RWY 12R
ST LOUIS LAMBERT INTL (STL)

MISSED APPROACH: Climb to 5000 on STL VORTAC R-128 to FONTI INT/STL 22.4 DME and hold, continue climb-in-hold to 5000.

4500 to PAULY
078° hdg (2.1) and
123° (1.7) (IF)

PAULY INT
I-LMR 17.8
RADAR

NAIKIN INT
I-LMR 12.5
RADAR

ST. LOUIS
117.4 STL
Chan 121

TUDNE INT
I-LMR 7.6
RADAR

LOCALIZER 109.7
I-LMR
Chan 34

Procedure NA for arrivals at
SADEN on V4 westbound.

ELEV 617

D	TDZE 12R 540
	TDZE 12L 541

Rwy 6-24 7603 X 150

MSA 2300
STL 2800

ALTERNATE MISSED APCH FIX
TROY
TOY
116.0
Chan 107

090°
270°
R-090

116.0 TOY
R-229
Chan 107

128°
308°

PAULY INT I-LMR 17.8 RADAR		NAIRN INT I-LMR 12.5 RADAR		TUDNE INT I-LMR 7.6 RADAR		I-LMR 3 I-LMR 1.9		5000 STL R-128 FONTI INT
VGS1 and ILS glidepath not coincident (VGS1 Angle 3.00/TCH 71).								
GS 3.00° TCH 54								
CATEGORY A B C D E								
S-ILS 12R 740/18 200 (200-½)								
S-LOC 12R 960/40 420 (400-¾)								
SIDESTEP 12L 980-1 439 (400-1) 980-1½ 439 (400-1½) 980-2 439 (400-2)								

NC-3, 01 OCT 2026 to 29 OCT 2026