

ILS or LOC RWY 9
BISHOP INTL (FNT)

MISSED APPROACH: Climb to 3000 on FNT VORTAC R-093 to HARRO/FNT VORTAC 10 DME/RADAR and hold.



CAUTION: Brightly lighted parking lot 4000' east of approach end of Rwy 27 can easily be confused for Rwy 27.

LOCALIZER 109.9
I-FNT

KROGR
FNT 6.5

274°
1 min
094°
2600
094°
(4)
(IF/IAF)
SELFY
FNT 10.6
RADAR

2600 to SELFY
275° (10.6)

FLINT
116.9 FNT
Chan 116

093°
273°
HARRO
FNT 10
RADAR
R-093

MSA FNT 25 NM
3100

Procedure NA for arrival on FNT VORTAC
airway radials 234 CW 286.

ELEV 782	D	TDZE 771
----------	---	----------

EC-1, 01 OCT 2026 to 29 OCT 2026

BISHOP INTL (FNT)
ILS or LOC RWY 9