

LOC/DME I-CLL 110.55 Chan 42(Y)	APP CRS 346°	Rwy Ldg TDZE 311 Apt Elev 321
---	------------------------	---

ILS or LOC RWY 35
EASTERWOOD FLD (CLL)

ADF or DME required for procedure entry. ADF or DME required for LOC only.	MALSR 	MISSED APPROACH: Climb to 2500 on I-CLL north course to DERRS INT/I-CLL 11.5 DME and hold.
--	-----------	--

ATIS 126.85	HOUSTON APP CON 134.3 360.85	EASTERWOOD TOWER ★ 118.5 (CTAF) 0 284.7	GND CON 128.7 284.7	UNICOM 122.95
-----------------------	--	---	-------------------------------	-------------------------




Diagram showing runway layout and headings:

- Runway 29: 5158 X 150
- Runway 11-29: 7000 X 150
- Runway 17-35: 35
- Headings: 346°, 166°

REIL Rwy 29
MIRL Rwy 11-29
HIRL Rwy 17-35

Diagram showing runway layout and headings:

- Runway 29: 5158 X 150
- Runway 11-29: 7000 X 150
- Runway 17-35: 35
- Headings: 346°, 166°

REIL Rwy 29
MIRL Rwy 11-29
HIRL Rwy 17-35

Diagram showing runway layout and headings:

- Runway 29: 5158 X 150
- Runway 11-29: 7000 X 150
- Runway 17-35: 35
- Headings: 346°, 166°

SC-5, 01 OCT 2026 to 29 OCT 2026

SC-5, 01 OCT 2026 to 29 OCT 2026