

YIGO, GUAM I, GUAM

TACAN Z RWY 06L

TACAN UAM Chan 54	APCH CRS 065°	Rwy Idg 10,527 TDZE 539 Arpt Elev 617
-----------------------------	-------------------------	--

APCH CRS
065°

Rwy Idg	10,527
TDZE	539
Arpt Elev	617

(USAF)

ANDERSEN AFB (PGUA)

	RADAR or DME required
--	-----------------------

T * When ALS inop, increase CAT AB RVR to 55, vis to 1 mile, CAT CDE vis 1 3/8 miles.

** Circling not authorized NW of Rwy 06L-24R.

SALS

MISSED APPROACH: Climb to 3000, intercept UAM R-051 to FOVEM and hold.

ATIS
118.175 254.325


GUAM APP CON/DEP CON
119.8 269.0

TOWER
126.2 233.7


GND CON
121.7 275.8

CAUTION: Environmentally Sensitive Area. Flights along Andersen cliffline restricted to 1000' AGL or above

All touchdown zones have a 1.0% down slope.



EMERG SAFE ALT 100 NM 2900



YIGO, GUAM I, GUAM

13°35'N - 144°56'E

ANDERSEN AFB (PGUA)

Amdt 4 14MAY26
TERPS

TACAN Z RWY 06L