

VORTAC MHZ <u>113.2</u> Chan 79	APP CRS 352°	Rwy Ldg 8500 TDZE 329 Apt Elev 346
---	------------------------	---

VOR/DME or TACAN RWY 34L

JACKSON-MEDGAR WILEY EVERS INTL (JAN)

T When local altimeter setting not received, use Hawkins Fld altimeter setting and increase all MDA 20 feet; increase S-34L Cats C/D/E visibility $\frac{1}{8}$ mile.
A Circling NA for Cat E southwest of Rwy 16R-34L. Helicopter visibility reduction below $\frac{3}{4}$ SM NA.
 ASR

MALSR

MISSED APPROACH: Climbing right turn to 3000 on heading 120° and MHZ VORTAC R-134 to RAKIN INT/ MHZ 16.5 DME and hold.

ATIS 121.05	JACKSON APP CON★ 123.9 317.7	JACKSON TOWER★ 120.9 (CTAF) 352.0	GND CON 121.7 348.6	UNICOM 122.95
----------------	---------------------------------	--------------------------------------	------------------------	------------------

