


VOR RWY 36
MERIDEN MARKHAM MUNI (MMK)

MISSED APPROACH: Climbing right turn to 2700 on HFD VOR/DME R-251 to MIDDLE INT/HFD 10.6 DME and hold, continue climb-in-hold to 2700.

UNICOM
123.05 (CTAF) **L**[illegible]