

KUSSO THREE DEPARTURE (RNAV)
(KUSSO3.KUSSO) 14MAY26


ROCKWALL, TEXAS
RALPH M HALL/ROCKWALL MUNI (F46)

LONE STAR DEP CON
124.3 282.275
CTAF
122.8

RNAV 1 - DME/DME/IRU or GPS required.
RADAR required.

**TOP ALTITUDE:
ASSIGNED BY ATC**

TAKEOFF MINIMUMS
Rwys 17, 35: Standard.



NOTE: BDDAY Transition: ATC assigned only.
NOTE: MRSSH Transition: For aircraft inbound to Shreveport,
Jackson and Monroe terminal area airports only.

(CONTINUED ON FOLLOWING PAGE)

NOTE: Chart not to scale.

(KUSSO3.KUSSO) 26134
AL-6323 (FAA)
KUSSO THREE DEPARTURE (RNAV)

ROCKWALL, TEXAS
RALPH M HALL/ROCKWALL MUNI (F46)



DEPARTURE ROUTE DESCRIPTION

When entering controlled airspace, fly heading assigned by ATC, expect RADAR vectors to SALVE, then on track 090° to KUSSO, then on assigned transition. Maintain ATC assigned altitude, expect filed altitude 10 minutes after departure.

- BDDAY TRANSITION (KUOSS3.BDDAY)
- BSKAT TRANSITION (KUOSS3.BSKAT)
- FORCK TRANSITION (KUOSS3.FORCK)
- LOOSE TRANSITION (KUOSS3.LOOSE)
- MRSSH TRANSITION (KUOSS3.MRSSH)
- ZAlea TRANSITION (KUOSS3.ZALEA)

SC-2, 01 OCT 2026 to 29 OCT 2026

SC-2, 01 OCT 2026 to 29 OCT 2026