CONTINUED FROM PRECEDING PAGE

AIRSPACE: CLASS D svc 1400–0600Z‡; other times CLASS E.
RADIO AIDS TO NAVIGATION: NOTAM FILE MWH.
MOSES LAKE (VH) (DH) VORW/DME 115.0 MWH Chan 97 N47°12.65´ W119°19.01´ at fld. 1193/18E.
VOR unusable:
025°–040° byd 40 NM
055°–070° byd 40 NM
071°–081° byd 40 NM blo 28,000´
175°–198° byd 40 NM blo 6,000´
175°–198° byd 67 NM blo 10,000´
175°–198° byd 70 NM
200°–210° byd 40 NM
220°–230° byd 40 NM
240°–253° byd 40 NM blo 18,000´
254°–260° byd 40 NM
315°–345° byd 40 NM
PELLY NDB (MHW/LOM) 408 MW N47°06.94´ W119°16.47´ 324° 5.9 NM to fld. 1136/18E.
ILS 109.5 I–MWH Rwy 32R. Class IB. LOM PELLY NDB. ILS and COMLO unmonitored when ATCT clsd.

• • • • • • • • • • • • • • • • • •

HELIPAD H1: H50X50 (ASPH)
HELIPAD H2: H50X50 (ASPH)

MOSES LAKE MUNI (W2Ø) 2 NE UTC–8(–7DT) N47°08.52´ W119°14.27´ — SEATTLE

1203 B NOTAM FILE SEA
RWY 16–34: H2513X50 (ASPH) S–8 MIRL
RWY 16: PAPI(P2L)—GA 3.0°. Thld dsplcd 466´. Tree.
RWY 34: PAPI(P2L)—GA 3.0°. Thld dsplcd 253´. Bldg. Rgt tfc.
SERVICE: S4
AIRPORT REMARKS: Unattended. Bird haz. Ultralgt opr reqd to obtain arpt safety briefing from arpt mgnt prior to initial use of arpt. Pilots bring own ropes.
AIRPORT MANAGER: (509) 764-3777
COMMUNICATIONS: CTAF/UNICOM 123.0
CLEARANCE DELIVERY PHONE: For CD ctc Grant County Apch at 509-762-2842, when Apch clsd ctc Seattle ARTCC at 253-351-3694.

MOSES LAKE N47°12.65´ W119°19.01´ NOTAM FILE MWH. — SEATTLE H–1C, L–13A

(VH) (DH) VORW/DME 115.0 MWH Chan 97 at Grant Co Intl. 1193/18E.
VOR unusable:
025°–040° byd 40 NM
055°–070° byd 40 NM
071°–081° byd 40 NM blo 28,000´
175°–198° byd 40 NM blo 6,000´
175°–198° byd 67 NM blo 10,000´
175°–198° byd 70 NM
200°–210° byd 40 NM
220°–230° byd 40 NM
240°–253° byd 40 NM blo 18,000´
254°–260° byd 40 NM
315°–345° byd 40 NM
RCO 122.4 (SEATTLE RADIO)

MOUNT CONSTITUTION N48°40.79´ W122°50.48´ — SEATTLE L–1E

RCO 122.3 (SEATTLE RADIO)

NORMAN GRIER FLD (See KENT on page 246)