ELMIRA/CORNING RGNL (ELM)(KELM) 6 NW UTC–5(–4DT) N42°09.59′ W76°53.50′
955 B TPA—See Remarks LRA ARFF Index—See Remarks NOTAM FILE ELM
RWY 06–24: H8001X150 (ASPH–GRVD) S–80, D–121, 2S–154, 2D–200 PCR 560 F/B/X/T HIRL CL
RWY 06: MALSR. REIL. VASI(V4L)—GA 3.0° TCH 51′. RVR–TMR Thld dsplcd 600′. Tree.
RWY 24: MALSR. REIL. PAPI(P4L)—GA 3.0° TCH 52′. RVR–TMR Thld dsplcd 202′. Tree.
RWY 10–28: H5404X150 (ASPH–GRVD) S–57, D–90, 2S–114, 2D–150 PCR 640 F/B/X/T MIRL
RWY 10: Trees.
RWY 28: PAPI(P4L)—GA 3.0° TCH 40′. Thld dsplcd 402′. Pole.
RWY 05–23: 2016X150 (TURF)
RUNWAY DECLARED DISTANCE INFORMATION

RWY 05:	TORA–2017	TODA–2017	ASDA–2017	LDA–2017
RWY 06:	TORA–8001	TODA–8001	ASDA–8001	LDA–7401
RWY 10:	TORA–5404	TODA–5404	ASDA–5004	LDA–5004
RWY 23:	TORA–2017	TODA–2017	ASDA–2017	LDA–2017
RWY 24:	TORA–8001	TODA–8001	ASDA–8001	LDA–7799
RWY 28:	TORA–5404	TODA–5404	ASDA–5404	LDA–5002

ARRESTING GEAR/SYSTEM
RWY 06: EMAS
SERVICE: S4 **FUEL** 100LL, JET A **OX** 4 **LGT** When twr clsd ACTIVATE MALSR Rwy 06 and 24, centerline lgts Rwy 06–24, HIRL Rwy 06–24, twy lights on Twy A, Twy A1, Twy A2, Twy A3, Twy B, Twy D, Twy J, Twy L, Twy T and Twy C north of Rwy 06–24—CTAF. When twr clsd MIRL Rwy 10–28; twy lights on Twy E, Twy G, Twy H and Twy C south of Rwy 06–24 not avbl. PAPI Rwy 24 unusable byd 9° rgt of centerline.
AIRPORT REMARKS: Attended continuously. Extensive glider activity on and invof arpt. Birds and deer on and invof arpt. Blimp activity rqr PPR, ctc arpt management at 607–426–5621. Class I, ARFF Index B. ARFF index C equipment coverage is avbl upon req ctc arpt management at 607–426–5621. TPA—2500(1545) reciprocating eng, 3000(2045) Turboprop/Jet. Rwy 10 opr prohibited for acft with apch speeds greater than or equal to 121 knots and/or wingspans greater than or equal to 118′. Acft with wing spans greater than 93′ should use extreme care when taxiing on Twy T adjacent to aprons. Rwy 05–23 (southeast of Rwy 06–24) unmarked seasonal use turf rwy clsd 1 Dec through 30 Apr. For land side access from apron when FBO clsd ctc ELM arpt attendant at 607–426–5621. Rwy 05–23 marked with asph L corner markers. Winter deicing on glycol apron only. Cold temperature airport. Altitude correction required at or below –21C. PAPI Twy H, Twy J, and Twy L limited to design Group II acft. Ldg fee for all non based acft. Terminal ramp is uncontrolled. Do not call for push/power back. Advise ground control when ready to taxi for dep. Twy T btn Twy L and Twy D non–movement area.
AIRPORT MANAGER: 607-739-5621
WEATHER DATA SOURCES: ASOS (607) 796–0065
COMMUNICATIONS: CTAF 121.1 **ATIS** 125.475 **UNICOM** 122.95
RCO 122.2 (BUFFALO RADIO)
Ⓡ **ELMIRA APP/DEP CON** 128.425 (1100–0500Z‡)
Ⓡ **NEW YORK CENTER APP/DEP CON** 133.35 (0500–1100Z‡)
ELMIRA TOWER 121.1 (1100–0500Z‡) **GND CON** 121.9 **CLNC DEL** 121.9
CLEARANCE DELIVERY PHONE: For CD if una to ctc on FSS freq, ctc New York ARTCC at 631-468-1425.
AIRSPACE: CLASS D svc 1100–0500Z‡; other times CLASS E.
TRSA svc ctc **APP CON** (within 15 NM)
RADIO AIDS TO NAVIGATION: NOTAM FILE IPT.
STONYFORK (L) (L) VORW/DME 108.6 SFK Chan 23 N41°41.72′ W77°25.19′ 048° 36.6 NM to fld. 1985/8W.
ILS 109.1 I–UEK Rwy 06. Class IA. Unmonitored when twr clsd.
ILS 109.1 I–ELM Rwy 24. Class IB. Unmonitored when twr clsd.
COMM/NAV/WEATHER REMARKS: For Clnc Del when twr clsd ctc Buffalo Radio on 122.2.