CONTINUED FROM PRECEDING PAGE

(L) TACAN Chan 12 LSV (135.5) N36º14.68´ W115º01.51´ at fld. 1863/12E. NOTAM FILE LSV.
No NOTAM MP: 1100–1500Z‡ Tue, Wed
TACAN AZIMUTH unusable:
003º–023º byd 24 NM blo 14,000´
024º–038º byd 30 NM blo 8,000´
039º–083º byd 30 NM blo 9,000´
039º–083º byd 35 NM
084º–158º byd 10 NM blo 14,000´
084º–158º byd 20 NM
290º–352º byd 20 NM blo 15,000´
353º–002º byd 18 NM blo 9,000´
353º–002º byd 24 NM blo 15,000´
DME unusable:
003º–023º byd 24 NM blo 14,000´
024º–038º byd 30 NM blo 8,000´
039º–083º byd 30 NM blo 9,000´
039º–083º byd 35 NM
084º–158º byd 10 NM blo 14,000´
084º–158º byd 20 NM
290º–352º byd 20 NM blo 15,000´
353º–002º byd 18 NM blo 9,000´
353º–002º byd 24 NM blo 15,000´
ILS 109.1 I–DIQ Rwy 21L. Class IE. ILS 21I DME from LSV TACAN and LAS VORTAC. No NOTAM MP: ILS 1100–1500Z‡ Thu. LOC unusable byd 25º right of course.
COMM/NAV/WEATHER REMARKS: (Call Bullseye SOF); Lcl emerg freq 343.725.

• • • • • • • • • • • • • • • • • •

HELIPAD H1: H100X100 (CONC)

NORTH FORK

STEVENS–CROSBY (Ø8U) 3 NW UTC–8(–7DT) N41º30.95´ W115º51.60´ **SALT LAKE CITY**
6397 NOTAM FILE RNO
RWY 01–19: 3600X50 (DIRT) 0.1% up N
RWY 19: Fence.
AIRPORT REMARKS: Unattended. First 800´ of Rwy 01 rough, uneven and rutted. Rwy 01 terrain drops off 150´ end of rwy.
AIRPORT MANAGER: 775-758-6409
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc Salt Lake ARTCC at 801-320-2568.

NORTH LAS VEGAS (See LAS VEGAS on page 403)