CONCORD MUNI (CON)(KCON) P (ARNG) 2 E UTC–5(–4DT) N43°12.16´ W71°30.14´ **NEW YORK**
342 B NOTAM FILE CON **H–11D, 12K, L–32H**
RWY 17–35: H6005X100 (ASPH) S–43, D–60 HIRL **IAP, AD**
RWY 17: PAPI(P4L)—GA 3.0° TCH 50´. Thld dsplcd 641´. Tree.
RWY 35: MALSR. VASI(V4L)—GA 3.0° TCH 50´. Trees.
RWY 12–30: H3200X75 (ASPH) S–30 MIRL
RWY 12: Antenna.
RWY 30: Ground.
SERVICE: S4 **FUEL** 100LL, JET A **LGT** ACTIVATE MALSR Rwy 35, HIRL Rwy 17–35, MIRL Rwy 12–30—CTAF. **MILITARY— FUEL** J8(Mil)–PPR (NC–100LL – Avbl H24 with credit card; A – Avbl 1230–2200Z‡, OT fone C603–228–2267 and flw prompts.)
AIRPORT REMARKS: Attended 1200–2200Z‡, exc Thanksgiving, Christmas, and New Years Day. Wildlife on and invof arpt. Hvy hel act 1 NM ESE of arpt 800 ft & blw. Self serve 100LL avbl 24 hrs with credit card. For Jet A aft hrs call 603–228–2267 & flw prompts. Rwy 35 designated calm wind rwy. Day & ngt VFR hel ops to & fm New Hampshire State Police hngr. Ops on National Guard twy & ramp prohibited wo prior cdn due to scty. Mil twy & ramp PCN R/A/W/T. Ops off paved sfcs prohibited due to conservation mgmt acts. Compass rose calibrated 2014.
AIRPORT MANAGER: 603-228-2267
WEATHER DATA SOURCES: ASOS 132.325 (603) 451–1106.
COMMUNICATIONS: CTAF/UNICOM 122.7
RCO 122.2 (BANGOR RADIO)
Ⓡ**BOSTON APP/DEP CON** 127.35
CLNC DEL 133.65
CLEARANCE DELIVERY PHONE: For CD ctc Boston Apch at 603-594-5552.
AIRSPACE: CLASS E.
RADIO AIDS TO NAVIGATION: NOTAM FILE CON.
(L) (L) VORW/DME 112.9 CON Chan 76 N43°13.19´ W71°34.53´ 123° 3.4 NM to fld. 715/15W.
VOR unusable:
022°–032° byd 20 NM blo 8,000´
190°–210° byd 12 NM blo 4,000´
318°–326° byd 30 NM blo 12,000´
DME unusable:
022°–032° byd 20 NM blo 8,000´
082°–110° byd 30 NM blo 5,000´
190°–210° byd 12 NM blo 4,000´
290°–300° byd 30 NM blo 7,000´
318°–326° byd 30 NM blo 12,000´
EPSOM NDB (LOM) 216 CO N43°07.13´ W71°27.16´ 353° 5.5 NM to fld. NDB unusable byd 20 NM.
ILS 108.7 I–CON Rwy 35. Class IA. LOM EPSOM NDB. NDB unusable byd 20 NM.

DEAN MEML (See HAVERHILL on page 149)

DILLANT/HOPKINS (See KEENE on page 150)

EPSOM N43°07.13´ W71°27.15´ NOTAM FILE CON. **NEW YORK**
NDB (MHW/LOM) 216 CO 353° 5.5 NM to Concord Muni. 355/16W. **L–32H, 33D**
NDB unusable:
Byd 20 NM

ERROL (ERR)(KERR) 1 NW UTC–5(–4DT) N44°47.53´ W71°09.87´ **MONTREAL**
1248 TPA—2048(800) NOTAM FILE BGR
RWY 15–33: 3600X60 (GRVL) 0.3% up SE
RWY 15: Trees.
RWY 33: Trees.
AIRPORT REMARKS: Unattended. For arpt information and conditions, call 603–482–3320. Wildlife on and invof arpt. Regular construction vehicle tfc on roadway at Rwy 33 end. 1:1 clearance slope. Rwy 15–33: Rwy soft in spring. Lrg patches of grass on rwy.
AIRPORT MANAGER: 603-616-8602
COMMUNICATIONS: CTAF/UNICOM 122.8
CLEARANCE DELIVERY PHONE: For CD ctc Boston ARTCC at 603-879-6859.

• • • • • • • • • • • • • • • • • •

HELIPAD H1: H61X61 (ASPH)
HELIPAD H1: Trees.
HELIPORT REMARKS: ACTIVATE helipad flood lgt and lighted windcone—CTAF.

FITZY N42°51.85´ W71°31.73´ NOTAM FILE MHT. **NEW YORK**
NDB (LOMW) 209 MJ 060° 5.8 NM to Manchester Boston Rgnl. 234/15W.