FERNLEY

SAMSARG FLD (N58) 3 S UTC–8(–7DT) N39°33.59′ W119°14.56′ **SAN FRANCISCO L–9A**
4346 B NOTAM FILE RNO
RWY 15–33: H3974X40 (ASPH)
RWY 15: Rgt tfc.
RWY 33: Hill.
RWY 05–23: 2750X30 (GRVL–DIRT)
RWY 05: Road.
RWY 23: Hill.
AIRPORT REMARKS: Attended Mon–Fri 1500–0300Z‡. Horse and cattle frqly on and invof rwys and twys. Rwy 05–23 eff gradient 4 percent W; dep Rwy 05 and arr Rwy 23 due to slp. Rwy 15–33 2–4′ ditches in the pri sfc and rwy safety area parallel to Rwy 10 ft from rwy edge. Rwy 15–33 eff gradient 2 percent S. Rwy 05–23 mnt wet sx rwy conds—amgr. 1740′ ovrn NW of Rwy 15 end not arpt property; may be mistaken for dsplcd thr. Arpt frqly clsd for model acft; remote acft ops on and invof arpt, rdo use encouraged. Hel trg rstrd to paved rwy ends; limit taxi and hover prac to ramp areas.
AIRPORT MANAGER: 775-471-7302
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc NorCal Apch at 916-361-0596.
RADIO AIDS TO NAVIGATION: NOTAM FILE RNO.
HAZEN (L) (L) VORTAC 114.1 HZN Chan 88 N39°30.98′ W118°59.86′ 266° 11.7 NM to fld. 4086/17E.
VOR unusable:
145°–155° byd 4 NM
300°–320° byd 30 NM blo 9,500′

FLYING M RANCH (See YERINGTON on page 427)

GABBS (GAB)(KGAB) 4 NW UTC–8(–7DT) N38°55.34′ W117°57.51′ **LAS VEGAS**
4699 NOTAM FILE RNO
RWY 09–27: 5950X65 (DIRT) 0.9% UP W
RWY 16–34: 2650X75 (DIRT) 0.9% UP N
SERVICE: **LGT** Arpt unlgtd; bcn lgt OTS indefly.
AIRPORT REMARKS: Unattended. No line of sight between Rwy 09–27 and Rwy 16–34. Jet actv N edge of tfc pat. Arr Rwy 09, dep Rwy 27, wind pmtg. Rwy 09–27 and Rwy 16–34 thr and edge mkd with reflectors. Rwy 09–27 and Rwy 16–34 thr and edge marked with reflectors; Rwy 09–27 and Rwy 16–34 reflective rods 240 ft fm EOR.
AIRPORT MANAGER: 775-751-6270
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc Oakland ARTCC at 510-745-3380.

GOLDFIELD

GOLDFIELD (1A8) 1 N UTC–8(–7DT) N37°43.32′ W117°14.18′ **LAS VEGAS**
5616 NOTAM FILE RNO
RWY 01–19: 3150X37 (GRVL)
RWY 01: Hill.
RWY 19: Sign. Rgt tfc.
SERVICE: **LGT** SS–SR
AIRPORT REMARKS: Unattended. Call for conditions 702–509–0059 or amgr. Ngt ops discouraged; mts all quads. Gnd north of Rwy 19 thr slopes down 10′ with gullys left and right; powerlines east of rwy. EMS heli adj to Rwy 01 thr. Arr uphill Rwy 19; dep downhill Rwy 01. Rwy 01–19 ruts on north side of rwy. Rwy 01 and 19 thld marked with white tires. 1′ berms around all rwys. Rwy 19 30′ drop 200′ fm thr left of cntrln.
AIRPORT MANAGER: 702-509-0059
COMMUNICATIONS: CTAF 122.9

• • • • • • • • • • • • • • • • • • •

HELIPAD H1: H100X100 (CONC) RWY LGTS(NSTD)

LIDA JUNCTION (ØL4) 14 S UTC–8(–7DT) N37°29.51′ W117°11.31′ **LAS VEGAS**
4684 NOTAM FILE RNO
RWY 18–36: 6100X80 (DIRT) 0.9% up N
AIRPORT REMARKS: Unattended. Rwy 18–36 uncntld vehicle & wildlife invof rwy. 30 ft unlgt pole 408 ft fm Rwy 18 thr on extdd cntrln. Rwy 18–36 thr, tdz, and edges mkd with tires.
AIRPORT MANAGER: (775) 485-3406
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc Nellis Apch at 702-652-4172.