DUNNELLON

MARION CO (X35) 5 E UTC–5(–4DT) N29°03.71′ W82°22.60′
65 B NOTAM FILE GNV
RWY 05–23: H5000X100 (ASPH) PCN 13 F/B/Y/T MIRL
RWY 05: PAPI(P4L)—GA 3.0° TCH 28′. Trees.
RWY 23: PAPI(P4L)—GA 3.0° TCH 27′. Tree.
RWY 10–28: H4701X60 (ASPH) PCN 12 F/A/Y/T MIRL
RWY 10: Trees.
RWY 28: Trees.
SERVICE: S4 **FUEL** 100LL, JET A+ **LGT** ACTVT PAPI Rwy 05 and 23; MIRL Rwy 05–23 and 10–28—CTAF.
AIRPORT REMARKS: Attended Mon–Fri 1300–2100Z‡. Credit card fuel avbl H24. Req 24 hr advance notice or immediate reporting upon ldg for acft equipped with wx modification or geoengineering eqpt 352–465–8545.
AIRPORT MANAGER: 352-465-8545
COMMUNICATIONS: CTAF/UNICOM 122.8
Ⓡ **JACKSONVILLE APP/DEP CON** 118.6
CLEARANCE DELIVERY PHONE: For CD ctc Jacksonville Apch at 904-741-0284.
RADIO AIDS TO NAVIGATION: NOTAM FILE OCF.
OCALA (VL) (L) VORTACW 113.7 OCF Chan 84 N29°10.65′ W82°13.58′ 229° 10.5 NM to fld. 78/0E.
TACAN AZIMUTH unusable:
025°–078°
329°–350°
351°–024° byd 28NM
VOR unusable:
010°–024° byd 40 NM
030°–037° byd 40 NM
053°–060° byd 40 NM
065°–077° byd 40 NM
094°–108° byd 40 NM blo 3,000′
094°–108° byd 66 NM
127°–137° byd 40 NM
157°–171° byd 40 NM blo 13,000′
157°–171° byd 75 NM
177°–187° byd 40 NM blo 2,000′
177°–187° byd 54 NM
193°–210° byd 40 NM
219°–244° byd 40 NM
277°–298° byd 40 NM
325°–335° byd 40 NM blo 10,000′
325°–335° byd 76 NM
352°–005° byd 111 NM
352°–005° byd 40 NM blo 12,000′
COMM/NAV/WEATHER REMARKS: Wx adv, click 4 times on CTAF.

JACKSONVILLE
H–8H, L–21D, 24F
IAP

