

ELLICOTT

**COLORADO SPRINGS EAST** (CO4) 3 NW UTC-7(-6DT) N38°52.46' W104°24.59'

**DENVER**

6145 NOTAM FILE COS

**L-10F**

**RWY 17L-35R:** 4500X40 (GRVL-DIRT)

**RWY 17L:** Berm.

**RWY 17R-35L:** H4500X42 (ASPH) S-6000 MIRL

**RWY 17R:** Fence.

**RWY 35L:** Road. Rgt tfc.

**RWY 08-26:** 3440X60 (GRVL-DIRT) S-60

**RWY 08:** Rgt tfc.

**RWY 26:** Road.

**SERVICE:** FUEL 100LL LGT ACTVT MIRL Rwy 17R-35L; call ahead 1 hour prior-amgr.

**AIRPORT REMARKS:** Unattended. Fuel by appt only. Coml acft fee-amgr. Glider ops invof of arpt. Rwy 08-26 2 in bump at Rwy 17R-35L intxn. Rwy 17R-35L CLSD to hel. Rwy 17R-35L thld mkgs worn and dfclt to read. Nstd segmented circle marked with white rocks. Nstd wind tee made fm barrels. Twin tandem rotary heli NA. ALERT: Mil trng invof Colorado Springs & Pueblo Colorado. Rwy 08 5 ft lgt pole R side of Rwy 35L 115 ft fm thr btw thr and PAPI; +35 ft pwr line 1500 ft fm thr both sides; +4 ft fence 125 ft fm cntrl N of rwy and W of Rwy 17R-35L intxn. Rwy 26 +4 ft fence 260 ft fm thr both sides; +15 ft bldg 130 ft L of thr; +15 ft road 240 ft fm thr both sides. Rwy 17L +5 ft berm 50 ft and 150 ft fm thr both sides. Rwy 17R +4 ft fence 100 ft R of rwy first 2500 ft; +4 ft fence 375 ft fm rwy end both sides; -2 ft trm 280 ft fm rwy end both sides. Rwy 17R and Rwy 35L thr red/green reflectors; rwy white reflectors both sides. Rwy 35L +4 ft fence 260 ft fm thr both sides; +15 ft road 250 ft fm thr both sides. 5 ft lgt pole R side btw thr and PAPI 115 ft fm thr. Rwy 35R +4 ft concrete box 100 ft fm thr 50 ft R of cntrl.

**AIRPORT MANAGER:** (719) 306-3021

**COMMUNICATIONS:** CTAF 122.9

**CLEARANCE DELIVERY PHONE:** For CD ctc Colorado Springs Apch at 719-556-9105.

**EMPIRE** OCO N39°47.67' W105°45.78'/12493

**DENVER**

AWOS-3 134.325

**L-9E**

**ERIE MUNI** (EIK)(KEIK) 3 S UTC-7(-6DT) N40°00.62' W105°02.89'

**CHEYENNE**

5119 B NOTAM FILE DEN

**L-10F, A**

**RWY 16-34:** H4700X60 (CONC) S-12.5 MIRL

**IAP**

**RWY 16:** REIL. PAPI(P2L)—GA 3.0° TCH 58'. Rgt tfc.

**RWY 34:** PAPI(P2L)—GA 3.0° TCH 52'. Tree.

**SERVICE:** S4 FUEL 100LL, JET A OX3, 4 LGT ACTVT REIL Rwy 16;

PAPI Rwy 16 and 34; MIRL Rwy 16-34—CTAF.

**AIRPORT REMARKS:** Attended Mon-Sat 1500-0000Z, Sun

1500-2100Z. Aft hr emerg—303-870-5659. Fuel: 100LL: Self svc avbl H24 with credit card. Twy A lgt. Rwy 16-34 -2 ft trm 60-70 ft E of cntrl full len. Rwy 16 has -2 to -6 ft ditch wi 700 ft of rwy end various locations. Rwy 34 30 ft road 1350 ft fm thr both sides; -6 to -12 ft ditch 60 ft L of cntrl parl to first 750 ft of rwy.

**AIRPORT MANAGER:** 303-664-0633

**WEATHER DATA SOURCES:** AWOS-3PT 133.825 (303) 604-4339.

**COMMUNICATIONS:** CTAF/UNICOM 123.0

® **DENVER APP/DEP CON** 125.125

**CLEARANCE DELIVERY PHONE:** For CD ctc Denver Apch at 303-342-1916.

**RADIO AIDS TO NAVIGATION:** NOTAM FILE BJC.

**JEFFCO (VH) (DH) VORW/DME** 115.4 BJC Chan 101 N39°54.78' W105°08.34' 025° 7.2 NM to fld. 5737/11E.

VOR unusable:

180°-225° byd 40 NM

226°-245° byd 36 NM blo 17,000'

246°-278° byd 30 NM blo 19,000'

279°-300° byd 34 NM blo 18,000'

301°-335° byd 40 NM

DME unusable:

246°-278° byd 30 NM

