



DEPARTURE ROUTE DESCRIPTION

TAKEOFF RUNWAY 6: Climbing right turn direct PMD VORTAC and hold, thence. . .

TAKEOFF RUNWAY 24: Climbing left turn direct PMD VORTAC and hold, thence. . .

. . . continue climb-in-hold to cross PMD VORTAC at or above MCA/MEA for route of flight.

VCOA ALL RUNWAYS: Obtain ATC approval for VCOA when requesting IFR clearance.  
Climb in visual conditions to cross General WM J Fox Airfield at or above 5900 before  
proceeding on course.