

COPTER ILS or LOC RWY 5

MALSR

MISSED APPROACH: Climb to 600 then climbing left turn to 2100 direct OTH NDB and hold, continue climb-in-hold to 2100.

SOUTHWEST OREGON RGNL (OTH)
COPTER ILS or LOC RWY 5