270 CANADA

```
SFATTI F
ABBOTSFORD BC (CYXX)
                             2 SW UTC-8(-7DT)
                                                      N49°01.52′ W122°21.60′
                                                                                                          H-1B, L-1E
  194 B AOE NOTAM FILE CYXX Not insp.
  RWY 07-25: H9597X200 (ASPH)
                                   HIRI
    RWY 07: SSALR, RFIL, Rgt tfc.
    RWY 25: ODALS, REIL, PAPI(P4L)—GA 3.0°, Thid dspicd 295'.
  RWY 01-19: H5328X200 (ASPH)
                                  MIRI
    RWY 01: REIL. PAPI(P4L)-GA 3.0°. Rgt tfc.
    RWY 19: REIL. PAPI(P4L)-GA 3.0°.
  RUNWAY DECLARED DISTANCE INFORMATION
     RWY 01: TORA-5328 TODA-6178 ASDA-5328 LDA-5328
    RWY 07: TORA-9597 TODA-10101 ASDA-9597 LDA-9597
    RWY 19: TORA-5328 TODA-5854 ASDA-5328 LDA-5328
    RWY 25: TORA-9597 TODA-10581 ASDA-9597 LDA-9302
  SERVICE: S4 FUEL 100LL, JET A
  AIRPORT REMARKS: Attended continuously. Fuel self-serve with credit card, 604-856-6260. ARFF svc avbl. Turbo-jet,
    turbo-fan, and turbo-prop not permitted from 0600-1500Z‡. All other ngt trng as authorized by arpt mgr. Parachute area
    aprx 5 NM NE of arpt. Prior ntc rqrd for cstms (1600-0800Z‡) call 888-226-7277. IFR trng flts PPR ctc
    604-775-9674. Helicopter trng on infld. Numerous obst in helicopter trng areas. Heli tng areas day use only. Oprs Itd
    winter maintenance 1430-0700Z‡. Other times 2 hrs prior ntc rqrd, call out charge. PPR dur winter maintenance exc
    scheduled ops, alternate or emerg, CRFI, PLR/PCN. Turf rwy clsd exc with prior permission and agreement plan with arpt
    mgr. Tall vehicles on road south of thId Rwy 01. Ltd parking and deicing dur winter ops, all wide body acft 24 hr prior ntc
    ctc ops 604-864-5544. Transit parking rstd to Apron 1. All other parking PPR ctc ops. Apron 1 north of Twy B, including
     Twy A, Itd to acft with wingspans of 118' or less. PPR for larger acft. Twy D unctl east of blast fence. Turns from Twy A
    onto Twy C rstd to C-130 smaller (blast issue). Twy G uncontrolled. Rwy 01-19, Twy B, C, C1, and C4 not avbl for acft
    taxiing when visibility below ½ SM. Night ops must use PAPI. Pilots should refer to Canadian Airport Charts (CAC) to
    obtain details on established hot spots, prior to operating on maneuvering areas. CAC are available for free on the NAV
     CANADA website.
  COMMUNICATIONS: ATIS 119.8 (1500-0700Z‡) 877-517-2847
    ABBOTSFORD RADIO (CYXX) on arpt 122.5
    VICTORIA TERMINAL APP/DEP CON 132 7
    TOWER 119.4 (inner) 121.0 (outer) (1500-0700Z‡) Mandatory freq 119.4 (0700-1500Z‡ below 4500′ MSL)
    GND CON 121 8 (1500-07007±)
  RADIO AIDS TO NAVIGATION: NOTAM FILE BLI.
     WHATCOM (H) VORTACW 113.0 HUH Chan 77 N48°56.72′ W122°34.76′ 041° 9.9 NM to fld. 83/20E.
    TACAN AZM unusable:
       155°-165° byd 15 NM blo 6,000°
    DME YAI 116.1 Chan 108X N49°01.07′ W122°22.57′
    ILS 109.7 I-IXX Rwy 07 LOC reliable only within 10° either side of centerline.
  COMM/NAV/WEATHER REMARKS: Local call to ABBOTSFORD FSS dial 604-852-2781. Pvt advsy svcs 877-270-2010. MF and
     advsv svc only provided over Canadian Territory.
                                                                                                            SEATTLE
ACTIVE PASS
                  BC N48°52.43′ W123°17.40′
    NDB(MHW) 378 AP 186° 14.6 NM to Victoria Intl./16E.
                                                                                                            L-1D, 1E
```

ANAHIM LAKE BC (CA 14) 1 S UTC-8(-7DT) N52°27.08′ W125°18.22′ 3639 NOTAM FILE CYWL Not insp.

I = 1D

RWY 13-31: H4642X75 (ASPH)

RUNWAY DECLARED DISTANCE INFORMATION

RWY 13: TORA-4642 TODA-4839 ASDA-4642 LDA-4642 RWY 31: TORA-4642 TODA-4839 ASDA-4642 LDA-4642

SERVICE: S4 FUEL 10011. JFT A

AIRPORT REMARKS: Attended 1800-2200Z‡ (DT 1700-2100Z‡) Mon, Wed, Fri O/T 3 hr PN. For attendance schedule call 250-742-2364. For fuel self-serve credit card. Exp moderate to extreme turbulence when winds from west. Extv float plane activity at Nimpo Lake, 9 NM SE of A/D. Possible presence of large animals within arpt perimeter. Rwy 31 down 0.59%. Ldg fees for coml acft.

AIRPORT MANAGER: 250-742-2364 COMMUNICATIONS: UNICOM 122.8

COMM/NAV/WEATHER REMARKS: Kamloops 866-WXBRIEF (Toll free within Canada) or 866-541-4101 (Toll free within Canada & USA), WxCam, Altimeter Itd hrs.