

**CORDOVA**

ANCHORAGE

**CORDOVA MUNI** (CKU) 1 E UTC-9(-8DT) N60°32.62' W145°43.55'

59 NOTAM FILE JNU

**RWY 06-24:** 1800X60 (GRVL) 0.5% up SW

**RWY 06:** Trees. Rgt tfc.

**RWY 24:** Road.

**SERVICE:** S4

**AIRPORT REMARKS:** Unattended. Rwy cond not monitored, recommend visual inspection prior to ldg. Birds invof arpt during summer months. Snow removal on irregular basis. Steep ridge and hill along North edge, strong East winds, rwy subj to strong downdrafts. Birds roost on South side, mountains 3 miles from AER 24. Busy residential road borders northside and parallels rwy. Larger grvl at AER24. Seaplane oprs in apch to Rwy 24. Rwy 06-24 marked with reflective cones. Rwy edge cones removed for winter 15 Oct thru 1 May.

**AIRPORT MANAGER:** 907-424-3202

**COMMUNICATIONS:** CTAF 122.5

**RCO** 123.6 122.2 (JUNEAU FSS)

**MOUNT EYAK RCO** 122.5 (JUNEAU FSS)

**RADIO AIDS TO NAVIGATION:** NOTAM FILE JNU.

**JOHNSTONE POINT (H) (H) VOR/DME** 116.7 JOH Chan 114

N60°28.86' W146°35.96' 063° 26.2 NM to fld. 48/18E.

wx cam

VOR unusable:

090°-124° byd 23 NM blo 8,000'

125°-188° byd 10 NM

DME unusable:

090°-124° byd 23 NM blo 12,000'

125°-191° byd 10 NM

**COMM/NAV/WEATHER REMARKS:** For a toll free call to Juneau FSS dial 1-866-297-2236.

**WATERWAY 09W-27W:** 8000X3000 (WATER)

**SEAPLANE REMARKS:** Unattended. No public seaplane dock. Public seaplane facilities at small boat harbor. Freeze up in winter; Tidewater remains open. Operates in Eyak Lake.

