

HARDING CO (See BUFFALO on page 366)

HAROLD DAVIDSON FLD (See VERMILLION on page 391)

HERREID MUNI (5T4) 1 N UTC-6(-5DT) N45°50.90' W100°04.44'

TWIN CITIES

1725 NOTAM FILE HON

RWY 12-30: H2230X200 (ASPH-TURF)

RWY 30: Road.

AIRPORT REMARKS: Unattended. Wildlife on and in/ov arpt. Rwy 12-30 marked with white & black tipped marker cones. Rwy 12 cultivation 80' from thld. Rwy 12-30 center 30' of rwy is asphalt.

AIRPORT MANAGER: (605) 437-2302

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Minneapolis ARTCC at 651-463-5588.

HIGHMORE MUNI (9DØ) 1 N UTC-6(-5DT) N44°32.45' W99°27.06'

TWIN CITIES

1854 B NOTAM FILE HON

RWY 13-31: H3701X60 (ASPH) MIRL 0.4% up SE

RWY 13: Fence.

SERVICE: S2

AIRPORT REMARKS: Unattended.

AIRPORT MANAGER: 605-871-9945

COMMUNICATIONS: CTAF 122.9

® MINNEAPOLIS CENTER APP/DEP CON 125.1

CLEARANCE DELIVERY PHONE: For CD ctc Minneapolis ARTCC at 651-463-5588.

RADIO AIDS TO NAVIGATION: NOTAM FILE PIR.

PIERRE (VL) (H) VORTACW 113.75 PIR Chan 84(Y) N44°23.67'

W100°09.77' 063° 31.8 NM to fld. 1791/11E.

VOR unusable:

005°-016° byd 40 NM blo 10,000'

005°-016° byd 88 NM

017°-023° byd 40 NM

L-12H

IAP

