CONTINUED FROM PRECEDING PAGE

AIRPORT MANAGER: 503-378-4880 COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Salt Lake ARTCC at 801-320-2568.

PACIFIC CITY STATE (PFC)(KPFC) 1 S UTC-8(-7DT) N45°11.96′ W123°57.71′

SEATTLE

10 NOTAM FILE MMV

RWY 14-32: H1860X30 (ASPH) S-7

RWY 14: Tree.

AIRPORT REMARKS: Unattended. Owner advises ctc with Department of Aviation 503–378–4880 prior to use. Rwy may be under water dur winter high tides. Ocnl driftwood on rwy due to flooding. Sfc conds not rprtd. Downwind ldgs not recommended and may not be possible. Many close in obst on both sides of rwy. Exp low level turbulence dur crosswind cond. Assorted trees and 40′ p–line at 500′ north of rwy. Pre–tkof engine run–ups to be conducted at the parking ramp only.

AIRPORT MANAGER: 503-378-4880

CLEARANCE DELIVERY PHONE: For CD ctc Seattle ARTCC at 253-351-3694.

KLAMATH FALLS

I_11A

PAISLEY (22S) 3 NW UTC-8(-7DT) N42°43.08′ W120°33.77′ 4395 B NOTAM FILE MMV

RWY 13–31: H4300X60 (ASPH) LIRL 0.4% up SE

AIRPORT REMARKS: Unattended. Rwy 13 has aiming points.

AIRPORT MANAGER: 541-947-4222 COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Seattle ARTCC at 253-351-3694.

RADIO AIDS TO NAVIGATION: NOTAM FILE LKV.

LAKEVIEW (H) (H) VORTACW 112.0 LKV Chan 57 N42°29.57′ W120°30.43′ 331° 13.7 NM to fld. 7465/19E.

PENDLETON

EASTERN OREGON RGNL AT PENDLETON (PDT)(KPDT) P (ARNG) 3 NW UTC-8(-7DT) N45°41.71′ SEATILE W118°50.60′ H-1C, L-13A

1494 B NOTAM FILE PDT

RWY 08–26: H6301X150 (ASPH–PFC) S–115, D–132, 2D–210

PCN 34 F/B/Y/U HIRL

RWY 08: ODALS. VASI(V4R)—GA 3.0° TCH 35′. RVR-R Ground. RWY 26: MALSR. PAPI(P4L)—GA 3.0° TCH 48′. RVR-T

RWY11-29: H4808X100 (ASPH-GRVD) S-70, D-120, 2S-152, 2D-122 PCN 18 F/B/Y/U MIRL

RWY 11: REIL. PAPI(P4L)—GA 3.0° TCH 46 '.

RWY 29: REIL, PAPI(P4R)—GA 3.0° TCH 48'.

RUNWAY DECLARED DISTANCE INFORMATION

 RWY 08: TORA-6301
 TODA-6301
 ASDA-6301
 LDA-6301


 RWY 11: TORA-4808
 TODA-4808
 ASDA-4808
 LDA-4808

 RWY 26: TORA-6301
 TODA-6301
 ASDA-6301
 LDA-6301

 RWY 29: TORA-4808
 TODA-4808
 ASDA-4808
 LDA-4808

SERVICE: S4 FUEL 100LL, JET A1+, MOGAS LGT When ATCT clsd ACTVT MALSR Rwy 26; ODALS Rwy 08; REIL Rwy 11 & 29; VASI Rwy 08, PAPI Rwy 11; HIRL Rwy 08–26; MIRL Rwy 11–29—CTAF. Rwy 11–29 PCL for hi intst 5 clicks only. PAPI Rwy 29 opr consly. REIL Rwy 11 OTS. REIL Rwy 29 OTS. MILITARY—FUEL (NC-100LL,

A1+ - Self svc avbl H24)



AIRPORT REMARKS: Attended 1400–04002‡. Svcs avbl from FBO btn 0400–14002‡ by phone call 541–276–3313 or 541–310–9542. Self fueling cardlocks avbl 24 hrs. Clsd to unscheduled air carrier ops with more than 30 pax seats exc PPR 4 hrs call 541–276–4411. Deer on and invof arpt Apr and Aug especially mornings and evenings. Thld Rwy 29 nstd marking, portion of rwy to function as twy. Twy B clsd south of Twy A. Int of ramp and Rwy 29 north end of terminal bldg, area obstructed from view of twr by terminal bldg. Rwy 08–26 surface condition unmonitored 1400–04002‡. Rwy 11–29 surface condition unmonitored 1400–04002‡. Fgt dly UAS actvty (lge and small) inside and invof the CDAS.

AIRPORT MANAGER: 541-276-7754

CONTINUED ON NEXT PAGE

194 OREGON

CONTINUED FROM PRECEDING PAGE

WEATHER DATA SOURCES: ASOS 118.325 (541) 278-2329.

 $\textbf{COMMUNICATIONS: CTAF}\ 119.7\ \textbf{UNICOM}\ 122.95$

PENDLETON RCO 122.2 (MC MINNVILLE RADIO)

® SPOKANE APP/DEP CON 133.15 (1400-0600Z‡) other times ctc

® SEATTLE CENTER 132.6

TOWER 119.7 (1400-0400Z‡) GND CON 121.9

CLEARANCE DELIVERY PHONE: When Apch clsd, for CD ctc Seattle ARTCC at 253-351-3694

AIRSPACE: CLASS D svc 1400-0400Z‡: other times CLASS E.

RADIO AIDS TO NAVIGATION: NOTAM FILE PDT.

VOR unusable:

057°-066° byd 40 NM

067°-078° byd 40 NM blo 29,000′

096°-106° byd 40 NM blo 8,300′ 096°-106° byd 48 NM blo 18,000

107°-117° byd 40 NM

118°-128° byd 40 NM blo 12,000′

118°-128° byd 75 NM

129°-207° byd 40 NM

ILS 110.3 I-PDT Rwy 26. Class IE. LOC and glideslope unmonitored when twr clsd.

COMM/NAV/WEATHER REMARKS: Emerg freq 121.5 not avbl at twr.

PINEHURST STATE (24S) 1 SW UTC-8(-7DT) N42°06.61′ W122°22.99′

KLAMATH FALLS

3643 NOTAM FILE MMV

RWY 04-22: H2800X30 (ASPH) 2.0% up SW

RWY 04: Trees.

RWY 22: Trees.

AIRPORT REMARKS: Unattended. Surface conditions not reported. Irregular winter maintenance. Arpt may be clsd by snow. Strong winds from any direction will likely cause low–level turbulence. Rwy 04–22 12 ft trees wi 25 feet of cntrin full len. Rwy 22 slopes up to the SW, with abrupt 4% rise on SW half of rwy. Owner advises contact Oregon Dept. of Aviation 503–378–4880 prior to use.

AIRPORT MANAGER: 503-378-4880 COMMUNICATIONS: CTAF 122.9

 $\label{eq:clearance} \textbf{CLEARANCE DELIVERY PHONE}: For \ \text{CD ctc Seattle ARTCC at } 253\text{-}351\text{-}3694.$

PITTSBURG LANDING (See IMNAHA on page 175)

PORTLAND

PORTLAND DOWNTOWN HELIPORT (61J) 0 N UTC-8(-7DT) N45°31.52′ W122°40.26′

SEATTLE

78 B NOTAM FILE MMV

HELIPAD H1: 80X80 (ROOF-TOP) S-25 PERIMETER LGTS

SERVICE: LGT For heliport PLASI when approaching flt apch and tkf 020–activate CTAF 3 times. When approaching flt apch and tkf 025–activate CTAF 5 times. When approaching flt apch and tkf 030–activate CTAF 7 times.

HELIPORT REMARKS: Unattended. +199´ radio twr (Igtd) 4950´ E of heliport in flt apch and tkf 025°. Helipad H1 yellow perimeter Igts, blue centerline twy Igts to helipads. Helipad H1 single heliport with 4 flt apchs 162°/220°/248°/295° and tkf directions 342°/040°/068°/115°. Arrow Igts for flt apch 220°/248°/295° and tkf 040°/068°/115°. Ldg fee.

AIRPORT MANAGER: 503-823-6677

COMMUNICATIONS: CTAF/UNICOM 123.075

 $\label{eq:clearance delivery Phone: For CD ctc Portland Apch at 503-493-7545.$