

COLLEGE PLACE

MARTIN FLD (S95) 1 W UTC-8(-7DT) N46°02.82' W118°25.03'

SEATTLE
L-13A

750 NOTAM FILE SEA

RWY 05-23: H3819X60 (ASPH) S-12 LIRL(NSTD)

RWY 05: VASI(V2L).

RWY 23: VASI(V2R). Road.

SERVICE: S2 FUEL 100LL LGT Rwy 05-23 NSTD LIRL southwest 1240' medium ints. Arpt lgtg opr from dusk until 1000Z±. ACTIVATE NSTD LIRL Rwy 05-23 and VASI Rwy 05 and Rwy 23—CTAF.

AIRPORT REMARKS: Attended Mon-Fri 1600-0100Z±. Call in advn 509-386-0000. 24 hr self svc credit card fueling facility. Gliders and other acft perform ops on turf btn Rwy 05-23 and twy. Overnight parking fee of \$3.00. Pvt road crosses 700' from southwest end of rwy. 2/3 of the rwy has wdsprr, opn, unsealed cracks and joints, hi lvl of raveling and alligator cracking. Ldg fee.

AIRPORT MANAGER: 509-386-0000

COMMUNICATIONS: CTAF/UNICOM 122.8

CLEARANCE DELIVERY PHONE: For CD ctc Spokane Apch at 509-742-2525, when Apch clsd ctc Seattle ARTCC at 253-351-3694.

RADIO AIDS TO NAVIGATION: NOTAM FILE ALW.

WALLA WALLA (VL) (DH) VORW/DME 116.4 ALW Chan 111 N46°05.22' W118°17.55' 231° 5.7 NM to fld. 1150/14E.

VOR unusable:

- 016°-071° byd 31 NM blo 12,500'
- 032°-042° byd 40 NM blo 12,500'
- 032°-042° byd 62 NM
- 042°-169° byd 40 NM
- 071°-101° byd 20 NM blo 14,500'
- 101°-146° byd 20 NM blo 13,500'
- 256°-285° byd 40 NM
- 286°-296° byd 40 NM blo 4,000'
- 286°-296° byd 50 NM
- 291°-302° byd 40 NM
- 309°-319° byd 40 NM blo 4,000'
- 309°-319° byd 85 NM
- 320°-031° byd 40 NM

DME unusable:

- 071°-101° byd 20 NM blo 14,500'
- 116°-071° byd 31 NM blo 12,500'
- 146°-151° byd 20 NM blo 11,500'

COLVILLE MUNI (63S) 1 E UTC-8(-7DT) N48°32.65' W117°53.01'

SEATTLE

1888 B NOTAM FILE SEA

RWY 01-19: H2695X40 (ASPH) S-11 MIRL

RWY 19: Tree.

SERVICE: FUEL 100LL LGT Dusk-dawn. ACTIVATE MIRL Rwy 01-19—CTAF.

AIRPORT REMARKS: Attended Mon-Fri 1600-0100Z±. Watch for deer on and in/ovf arpt. Rwy 19 dthr 255'. When ldg Rwy 19, bright lgts around high school stadium, aprx 3/4 miles south of arpt. Ocnl vehicular tfc across end of Rwy 01-19 and twy. Grass ldg area avbl across Rwy 01-19 1500' X150'. Hazards are 50' obst on both ends, trees/poles. Apron and tiedown grvl; 3 asph paved transient tiedowns westside. Eastside tiedowns gravel. 2 car avbl.

AIRPORT MANAGER: 509-685-9056

WEATHER DATA SOURCES: AWOS-3 119.275 (509) 684-8994.

COMMUNICATIONS: CTAF/UNICOM 122.8

CLEARANCE DELIVERY PHONE: For CD ctc Seattle ARTCC at 253-351-3694.

CONCRETE

MEARS FLD (3W5) 1 S UTC-8(-7DT) N48°31.79' W121°45.49'

SEATTLE

267 NOTAM FILE SEA

RWY 07-25: H2609X60 (ASPH) S-12

RWY 07: Trees. Rgt tfc.

RWY 25: Trees.

SERVICE: FUEL 100LL

AIRPORT REMARKS: Unattended. Elk and deer freq both rwy ends and mid-fld. All patterns south of arpt.

AIRPORT MANAGER: 425-322-8582

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Seattle ARTCC at 253-351-3694.

HELIPAD H1: H40X40 (CONC)

HELIPORT REMARKS: Helipad for emerg use only.