LOF	27
LUI	FISHERMANS BAY SPB (81W) 1 N UTC-8(-7DT) N48°30.99' W122°55.08' SEATLLE OO NOTAM FILE SEA WATERWAY 05W-23W: 3000X150 (WATER) WATERWAY 05W-23W: 3000X150 (WAT
	LOPEZ ISLAND (S31) 3 N UTC-8(-7DT) N48°29.04' W122°56.26' SEATTLE 209 B NOTAM FILE SEA RWY 16-34: H2905X61 (ASPH-GRVD) S-12.5 MIRL 1.6% up N RWY 16: REIL. PAPI(P2L)—GA 4.0° TCH 43'. Trees. Rgt tfc. RWY 34: REIL. PAPI(P2L)—GA 4.0° TCH 33'. Trees. AIRPORT REMARKS: Unattended. Rwy 16-34 soft shoulders and thids. AIRPORT MANAGER: 360-468-4116 COMMUNICATIONS: CTAF 128.25 CLEARANCE DELIVERY PHONE: For CD ctc Whidbey Apch at 360-257-3310.
	LOST RIVER (See MAZAMA on page 245)
	LOWER GRANITE STATE (See COLFAX on page 225)
	LOWER MONUMENTAL STATE (See KAHLOTUS on page 239)
	LYNDEN MUNI/JANSEN FLD (38W) 1 N UTC-8(-7DT) N48°57.35' W122°27.49' 106 B NOTAM FILE SEA RWY 08-26: H2425X40 (ASPH) S -12 RWY LGTS(NSTD) RWY 08: PAPI(P2L)—GA 3.0° TCH 15'. ThId dsplcd 262'. Trees. RWY 26: PAPI(P2L)—GA 6.0° TCH 15'. ThId dsplcd 422'. Trees. RUNWAY DECLARED DISTANCE INFORMATION RWY 08: LDA-2163 RWY 26: TORA-2425 LDA-2003 SERVICE: FUEL 100LL LGT Use 3 clicks to ACTVT MIRL Rwy 08-26 and rotating bcn—CTAF. AIRPORT REMARKS: Unattended. Automated credit card system for fuel. Exposed ditch Rwy 08-26. Avoid night Indgs to Rwy 26—night Indgs should be performed on Rwy 08—winds permitting. 1850 ft btn thr Igts; Rwy 08 thr Igts located 134 ft prior to dsplcd thr. Rwy 08 thr reltd 155 ft for ngt opns; Rwy 26 thr reltd 434 ft for ngt opns; 1871 ft Igtd at night. No white/red Igts past dsplcd thId. Run-ups not permitted on Rwy 26 turn around taxiway. Fly PAPI on all approaches to Rwy 08. WSDOT Kiosk Ictd at fuel stn. Bicycles avbI in pilot's lounge. AIRPORT MANAGER: 360-354-3446 COMMUNICATIONS: CTAF 122.9 VICTORIA TERMINAL APP/DEP CON 132.7 290.8 604–586–4560 COMMUNICATIONS: CTAF 122.9
	MANSFIELD (8W3) 0 E UTC-8(-7DT) N47°48.56' W119°38.22' SEATLE 2272 B NOTAM FILE SEA RWY 03-21. H2575X46 (ASPH) LIRL RWY 03: Road. RWY 21. Road. RWY 21. Road. RWY 21. TORA-2400 RWY 03: TORA-2400 RWY 21: TORA-2400 SERVICE: LGT Rwy 03-21 no rwy Igts northside of Rwy 21 end to midfield. Bcn tempo OTS. AIRPORT REMARKS: Unattended. Possible turbulence from grain elevators north side of arpt. Rwy 03-21 has widespread, open unsealed cracks and joints. NW prkg has steep dropoff. Rwy 03-21 markings faded. Pilots bring own ropes. Lgtd wind tee. AIRPORT MANAGER: 509-884-4700 COMMUNICATIONS: CTAF 122.9 CI EFABRIC FEILVIEP PUNDIF: Err CD ctr. Seattle ARTCC at 253-351-3694

CLEARANCE DELIVERY PHONE: For CD ctc Seattle ARTCC at 253-351-3694.

MARTIN FLD (See COLLEGE PLACE on page 226)

244