

TINIAN ISLAND**FRANCISCO MANGLONA BORJA/TINIAN INTL** (TNI)(PGWT) 1 N UTC+10 N14°59.95'**HAWAIIAN-MARIANA**

E145°37.16'

270 B Class I, ARFF Index A NOTAM FILE HNL

P-1A**RWY 08-26:** H8600X151 (ASPH-CONC-GRVD) S-75, D-200, 2D-400, 2D/2D2-832**IAP**

PCN 61 F/A/X/T MIRL 0.4% up E.

RWY 08: REIL. PAPI(P4L)—GA 2.98° TCH 43'. Hill.**RWY 26:** REIL. PAPI(P4L)—GA 2.99° TCH 45'. Rgt tfc.**RUNWAY DECLARED DISTANCE INFORMATION****RWY 08:** TORA-8600 TODA-8600 ASDA-8600 LDA-8600**RWY 26:** TORA-8600 TODA-8600 ASDA-8600 LDA-8600**SERVICE:** LGT For REIL Rwy 08 and Rwy 26, PAPI Rwy 08 and Rwy 26, MIRL Rwy 08-26, ctc airport 2000-1000Z on CTAF 123.6. For emergencies between 1000-2000Z lgts can be requested by contacting port police (670) 433-9295/9294 or CTAF 123.6**AIRPORT REMARKS:** Attended 2000-1000Z, other times PPR from Commonwealth Ports Authority Tinian manager, Tinian call 670-433-9296/94 Mon-Sun. Arpt CLSD to unscheduled air carrier operations with more than 10 pax seats except 24 hrs PPR rqrd in writing to arpt manager. P.O. Box 235, Tinian MP 96952. ARFF svc available 2000-0930Z and for air carrier ops with more than 9 passenger seats. Cust avbl dur sked ops. OTR times prior arrangements must be made with Customs Border Patrol Protection Saipan call 288-0028. Traffic pattern altitude for large and turbine powered acft 1803(1532); small acft 1303(1032).**AIRPORT MANAGER:** (670) 433-9294**COMMUNICATIONS:** CTAF 123.6

® GUAM CERAP APP/DEP CON 118.4

RADIO AIDS TO NAVIGATION**SAIPAN NDB (HW)** 312 SN N15°06.68' E145°42.62' 216° 8.7 NM to fld. 83/2E.