

PORT MANSFIELD**CHARLES R JOHNSON** (TØ5) 1 NW UTC-6(-5DT) N26°33.61' W97°26.36'**BROWNSVILLE**

10 B NOTAM FILE SJT

L-20H, 21A

RWY 12-30: H3200X50 (ASPH) S-21 MIRL**RWY 12:** P-line.**RWY 30:** P-line.**SERVICE:** LGT MIRL Rwy 12-30 preset low intst; to increase intst ACTVT—CTAF.**AIRPORT REMARKS:** Unattended. Harbor superintendent's ofc attended 1400-2250Z†. Deer & birds on & invof arpt. Rwy 12 and Rwy 30 rwy mkgs discolored. Fee for ovnght tie down.**AIRPORT MANAGER:** 956-944-2325**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Corpus Christi Apch at 361-299-4230.**RADIO AIDS TO NAVIGATION:** NOTAM FILE HRL.**HARLINGEN (L) (L) VOR/DME** 113.65 HRL Chan 83(Y) N26°13.75' W97°39.14' 025° 22.9 NM to fld. 32/5E.**PORTLAND****HUNT** (9R5) 2 NW UTC-6(-5DT) N27°53.20' W97°20.98'**BROWNSVILLE**

40 NOTAM FILE SJT

RWY 14L-32R: H2650X20 (ASPH) S-9 0.6% up NW**RWY 14L:** P-line. Rgt tfc.**RWY 32R:** Brush.**RWY 14R-32L:** 1400X60 (TURF-GRVL)**RWY 14R:** Rgt tfc.**NOISE:** Noise abatement procedures in effect. Call arpt manager at 361-643-3950.**AIRPORT REMARKS:** Unattended. Rwy 14R-32L CLOSED indef. Wind turbines N of arpt. Rwy 14L-32R has severe grass encroachment, pot holes, and loose gravel on rwy. Rwy 14R-32L heavy rutting along entire rwy length. Rwy 14L-32R limited line of sight between thlds; southern 600' of rwy drops off approximately 8'. Rwy 32R ground drops off approximately 10' at thld.**AIRPORT MANAGER:** 361-643-3950**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Corpus Christi Apch at 361-299-4230.**POSSUM KINGDOM** (See GRAFORD on page 324)