


RNAV (GPS) RWY 24


HEBER SPRINGS MUNI (HBZ)

Procedure NA at night. Rwy 24 helicopter visibility reduction below 1 SM NA. Obtain local altimeter setting on CTAF; when not received, use Batesville altimeter setting and increase all MDAs 80 feet; and increase LNAV visibility Cat B $\frac{1}{4}$ SM, Cat C and D $\frac{1}{2}$ SM. Increase Circling visibility Cat B, C $\frac{1}{4}$ SM, and Cat D $\frac{1}{2}$ SM.

MISSED APPROACH: Climb to 4000 direct RILVE and hold, continue climb-in-hold to 4000.

UNICOM
122.7 (CTAF) **L**

TDZE 632



35°31'N-92°01'W

HEBER SPRINGS MUNI (HBZ)
RNAV (GPS) RWY 24