HOT SPOTS

An "airport surface hot spot" is a location on an aerodrome movement area with a history or potential risk of collision or runway incursion, and where heightened attention by pilots/drivers is necessary.

A "hot spot" is a runway safety related problem area on an airport that presents increased risk during surface operations. Typically it is a complex or confusing taxiway/taxiway or taxiway/runway intersection. The area of increased risk has either a history of or potential for runway incursions or surface incidents, due to a variety of causes, such as but not limited to: airport layout, traffic flow, airport marking, signage and lighting, situational awareness, and training. Hot spots are depicted on airport diagrams as open circles or polygons designated as "HS 1", "HS 2", etc. and tabulated in the list below with a brief description of each hot spot. Hot spots will remain charted on airport diagrams until such time the increased risk has been reduced or eliminated.

	HOT SPOT	
CITY/AIRPORT	HOT SPOT	DESCRIPTION*
AKRON, OH		
AKRON-CANTON RGNL (CAK)	HS 1	ILS hold short line proximity to transient parking ramp.
(4,	HS 2	Rwy 01-19 and Rwy 05-23 hold short line on Twy C
		east of Rwy 01-19.
	HS 3	Hold short lines on Twy K between Rwy 01-19 and Rwy
		05-23 are nearly co-located.
CINCINNATI, OH		
CINCINNATI MUNI/		
LUNKEN FLD (LUK)	HS 1	Twy C and Rwy 03L apch area.
	HS 2 HS 3	Twy A and Rwy 21R. Departing acft on Rwy 21L can expect to hold short of Rwy
	поз	25 on Twy A.
	HS 4	Terminal ramp and Rwy 07, need ATC authorization to
		depart terminal ramp area.
CLEVELAND, OH		·
BURKE LAKEFRONT (BKL)	HS 1	Short taxi distance from the ramp to Rwy 06 L/R. Twy Alpha often
		missed.
COLUMBUS, IN		
COLUMBUS MUNI (BAK)	HS 1	Twy A and Twy B.
COLUMBUS, OH		
OHIO STATE		
UNIVERSITY (OSU)	HS 1	When holding short of Rwy 09R, aircraft must clear Rwy 05
		hold short line on Twy A, west of Rwy 05.
	HS 2	Rwy 05 hold short line close proximity to west ramp on Twy A.
	HS 3	Int Rwy 27R, Rwy 23 -wrong rwy departure risk.
COLUMBUS, OH		
JOHN GLENN COLUMBUS INTL (CMH)	HS 1	Area not visible from the twr.
INTE (CIVIH)	пот	Area not visible nom the twi.
DAYTON, OH		
JAMES M COX DAYTON		
INTL (DAY)	HS 1	Taxiing via Twy D, Rwy 36, Twy H.
EVANSVILLE, IN	110.4	Total Country December 40,000 mars in all an appropriate of annual December 40,000 mars in all and appropriate of annual December 40,000 mars in all and appropriate of annual December 40,000 mars in all and appropriate of annual December 40,000 mars in all and appropriate of annual December 40,000 mars in all and appropriate of annual December 40,000 mars in all and appropriate of annual December 40,000 mars in all and appropriate of annual December 40,000 mars in all and appropriate of annual December 40,000 mars in all and appropriate of annual December 40,000 mars in all and appropriate of annual December 40,000 mars in all annual Dece
EVANSVILLE RGNL (EVV)	HS 1	Twy G and Rwy 18-36, rwy in close proximity of ramp. Be prepared to hold short of the rwy entering twy G.
	HS 2	Rwy 27 and Twy A.
FORT WAYNE, IN	110 2	TWY 27 Cita TWY 7.
FORT WAYNE INTL (FWA)	HS 1	Short taxi distance from West Ramp when departing C2 int.
,		Aircraft tend to miss turn onto TWY C from West Ramp.
LAFAYETTE, IN		
PURDUE UNIVERSITY (LAF)	HS 1	Complex int Twy B, Twy B3, Twy C.
VOLINGOTOWALANA PRESS. CO.		
YOUNGSTOWN/WARREN, OH YOUNGSTOWN/WARREN		
RGNL (YNG)	HS 1	Twy H and Rwy 05-23, rwy in close proximity of ramp. Be
NONE (INO)	110 1	prepared to hold short of the rwy entering Twy H.
		rr

30 NOV 2023 to 28 DEC 2023