24081

HOT SPOTS				
An "airport surface hot spot" is a location on an aerodrome movement area with a history or potential risk of collision or runway incursion, and where heightened attention by pilots/drivers is necessary.				
A "hot spot" is a runway safety related problem area on a irport that presents increased risk during surface opera- tions. Typically it is a complex or confusing taxiway/taxiway or taxiway/runway intersection. The area of increased risk has either a history of or potential for runway incursions or surface incidents, due to a variety of causes, such as but not limited to: airport layout, traffic flow, airport marking, signage and lighting, situational awareness, and training. Hot spots are depicted on airport diagrams as open circles or polygons designated as "HS 1", "HS 2", etc. and tabulated in the list below with a brief description of each hot spot. Hot spots will remain charted on airport diagrams until such time the increased risk has been reduced or eliminated.				
CITY/AIRPORT HC	T SPOT	DESCRIPTION*		
BEDFORD, MA LAURENCE G HANSCOM FLD (BED)	HS 1	Confusing twy int.		
BEVERLY, MA BEVERLY RGNL (BVY)	HS 1 HS 2	Rwy hold line at East Ramp exit. Int of Twy E and Twy H.		
BOSTON, MA GENERAL EDWARD LAWRENCE LOGAN INTL (BOS)	HS 1	Maintain vigilance when taxiing on Rwy 15L-33R apch Rwy 04L-22R.		
	HS 2 HS 3 HS 4	Twy N and Rwy 15R-33L. Maintain vigilance on Twy E and Twy K when apch Rwy 04L-22R. Maintain vigilance on Twy C when apch Rwy 09-27. Maintain vigilance on Twy D when apch Rwy 15R-33L.		
BURLINGTON, VT PATRICK LEAHY BURLINGTON INTL (BTV)	HS 1 HS 2 HS 3 HS 4	Twy A between Rwy 15-33 and Rwy 01-19. Sm space. Int of Rwys 15-19 and Twy A. Confusing int. Int of Twy B at Rwy 01-19. Guard Igts. Int of TWY C at Rwy 01-19. Guard Igts.		
DANBURY, CT DANBURY MUNI (DXR)	HS 1 HS 2 HS 3	Maintain vigilance confusing twy configuration. Pilots unfamiliar should ask for progressives. Area not visible from the twr. Active ramp adjacent to twy.		
GROTON (NEW LONDON), CT GROTON-NEW LONDON (GON)	HS 4 HS 1 HS 2	Hold position on Twy C for Rwy 26. Rwy 15-33 at Twy C and Twy B. Rwy 15-33 at Twy J and Twy B.		
HARTFORD, CT HARTFORD-BRAINARD (HFD)	HS 1	Twy A and Twy H near the helipad.		
LAWRENCE, MA LAWRENCE MUNI (LWM)	HS 1 HS 2	Rwy 05-23 and Twy E. Rwy 14-32 and Twy A.		
LEBANON, NH LEBANON MUNI (LEB)	HS 1 HS 2	Unusual location for rwy hold position marking on Twy B for Rwy 25. A portion of Twy B and North Ramp not visible from the control twr.		
NANTUCKET, MA NANTUCKET MEML (ACK)	HS 3 HS 1 HS 2 HS 3 HS 4	Acft routinely back taxi on Rwy 18-36. High traffic area. High traffic area. High traffic area. Twy H and Twy E.		

(SEE CONTINUATION PAGE FOR MORE LISTINGS)

		HOT SPOTS
		(CONTINUED)
CITY/AIRPORT	HOT SPOT	DESCRIPTION*
PORTLAND, ME		
PORTLAND INTL		
JETPORT (PWM)	HS 1	Twy C and Twy A in close proximity of Rwy 11-29.
	HS 2	Acft taxiing northbound on Twy C must maintain vigilance
		apch the Rwy 18 hold short marking which is located
		further south on Twy C than most pilots would anticipate.
PROVIDENCE, RI		
RHODE ISLAND TF GREEN		
INTL (PVD)	HS 1	Complex twy int in close proximity of rwy.
	HS 2	Complex rwy/twy int.
	HS 3	Complex twy int in close proximity of rwy.
	HS 4	Maintain vigilance dep northwest ramp. Twy S is immed adj to northwest ramp. Acft could inadvertently enter Rwy 16-34.
	HS 5	Hold short line Rwy 34 and Twy C.
WESTFIELD/SPRINGFIELD, MA		· ·
WESTFIELD-BARNES RGNL (BA	(F) HS 1	Maintain vigilance departing ramp. Twy A and Twy B complex int in close proximity to Rwys.
	HS 2	Unusual location for Rwy hold position marking on Twy A for Rwy
	п 5 2	15.
WINDSOR LOCKS, CT		
BRADLEY INTL (BDL)	HS 1	Aircraft on Twy S missing Twy C may enter Rwy 24.
	HS 2	Aircraft on Twy D missing Twy S may enter Rwy 33.

22251

*See appropriate Chart Supplement HOT SPOT table for additional information.

21 MAR 2024 to 18 APR 2024