

NOTE: RADAR required.

NOTE: RNAV 1.


NOTE: DME/DME/IRU or GPS required.

NOTE: Expect Rwy 21L.

**NOTE:** Jet aircraft descend via Mach number until intercepting 280K. Maintain 280K until slowed by the STAR.

280K. Maintain 280K until slowed by the STAR.

**NOTE:** For use when DTW landing south or west. When DTW landing north, file and expect the WNGNT RNAV STAR.



NOTE: Chart not to scale.

## ARRIVAL ROUTE DESCRIPTION

## JACCI TRANSITION (JACCI.FERRL2)

From WINGNT on track 268° to cross FERRL between 8000 and 10000, then on track 268° to cross GMOIR at 7000, then on track 306° to cross CHEWZ at 6000 and at 210K, then on track 306° to cross COBBO at 6000 and at 210K, then on track 306°. Expect RADAR vectors to final approach course.

LOST COMMUNICATIONS:

From COBBO, execute ILS Rwy 21L approach.

## FERRL TWO ARRIVAL (RNAV)

(WNGNT.FERRL2) 10OCT19

DETROIT, MICHIGAN

DETROIT METRO WAYNE COUNTY (DTW)