


21168

ILS RWY 21L (SA CAT I & II)
DETROIT METRO WAYNE COUNTY (DTW)

MISSED APPROACH: Climb to 1100 then climbing left turn to 4000 on DXO R-122 to GAAGE/DXO 16 DME and hold, continue climb-in-hold to 4000.

GND CON		CLNC DEL	CPDLC
121.8 (NW)	119.45 (NE)	120.65	
127.25 (SW)	119.25 (SE)		



**SA CATEGORY I & II ILS - SPECIAL AIRCREW
& AIRCRAFT CERTIFICATION REQUIRED**

HIRL all runways
REIL Rwy's 3L, 9L, 9R and 21R
TDZ/CL Rwy's 3R, 4L, 4R and 22R

42°13'N-83°21'W

DETROIT METRO WAYNE COUNTY (DTW)
ILS RWY 21L (SA CAT I & II)