

HUNTSVILLE, ALABAMA

AL-5924 (FAA)

22195



| | | | |
|---------------------------------------|------------------------|-----------------------------|--|
| VORTAC RQZ 112.2 Chan 59 | APP CRS 043° | Rwy Idg TDZE Apt Elev | N/A N/A 764 |
|---------------------------------------|------------------------|-----------------------------|--|

VOR-B

HUNTSVILLE EXEC TOM SHARP JR FLD (MDQ)

| | | | |
|---------------|--|---|--|
| DME required. | | MISSED APPROACH: Climbing left turn to 3000 direct RQZ VORTAC and hold. | |
|---------------|--|---|--|

| | | | |
|--------------------------|---|-----------------------|---------------------------------|
| AWOS-3PT 120.0 | HUNTSVILLE APP CON* 125.6 354.1 | GCO 121.725 | UNICOM 123.0 (CTAF) 0 |
|--------------------------|---|-----------------------|---------------------------------|



HUNTSVILLE, ALABAMA
Amdt 7B 28FEB19

HUNTSVILLE EXEC TOM SHARP JR FLD (MDQ)
34°52'N-86°33'W

VOR-B

SE-4, 26 DEC 2024 to 23 JAN 2025

SE-4, 26 DEC 2024 to 23 JAN 2025