

HI-TACAN B

TACAN DHK Chan 36	APCH CRS 326°	Rwy ldg TDZE N/A Arprt Elev 761
--------------------------	----------------------	---

[USAF]

RANDOLPH AFB (KRND)


RADAR required for missed approach monitoring

* Circling not authorized SW of Rwy 15L-33R.

MISSED APPROACH: Track 327° to 1500, then climbing right turn heading 084° to 3000. Intercept DHK TACAN R-054 direct WIMVI and hold.


ATIS ★ 290.525	SAN ANTONIO APP CON 128.05 318.1	TOWER ★ 128.25 294.7	GND CON 119.65 275.8	CLNC DEL (RWY 15L-33R) 338.35	HANGOVER ATIS ★ 327.8	HANGOVER TOWER ★ 120.5 291.1	HANGOVER GND CON 124.75 353.75
-----------------------	---	-----------------------------	-----------------------------	--------------------------------------	------------------------------	-------------------------------------	---------------------------------------

•1585



EMERG SAFE ALT 100 NM 4100

ELEV **761**



HIRL all rwys
ALS Rwy 15L nstd len 2100'

1500	3000	DHK R-054	WIMVI DHK 15	
↑ tr 327°	↻ hdg 084°			
CATEGORY		C	D	E
CIRCLING*		1260-1½ 499 (500-1½)	1900-3	1139 (1200-3)

HI-TACAN B

SC-3, 20 FEB 2025 to 20 MAR 2025