


LOC/DME I-AQI 111.75	APP CRS 101°	Rwy Idg 10113 TDZE 809 Apt Elev 815
Chan 54 (Y)		

ILS RWY 10R (SA CAT I & II)

JOHN GLENN COLUMBUS INTL (CMH)


ADF required. DME or RADAR required.

Simultaneous approach authorized.
SA CAT I, SA CAT II: Requires specific OPSPEC, MSPEC, or LOA approval.

MALSR 

MISSED APPROACH: Climb to 1400 then climbing right turn to 3000 direct BU LOM and hold.



D-ATIS 124.6	COLUMBUS APP CON 125.95 371.975	COLUMBUS TOWER 132.7 257.8	GND CON 121.9 348.6	CLNC DEL 126.3	CPDLC
------------------------	---	--------------------------------------	-------------------------------	--------------------------	-------



EC-2, 20 MAR 2025 to 17 APR 2025

EC-2, 20 MAR 2025 to 17 APR 2025

ELEV 815	D TDZE 809
----------	-------------------



CATEGORY	A	B	C	D
S-ILS 10R	SA CAT I	RA 146/14	150 DA 959	
S-ILS 10R	SA CAT II	RA 99/12	100 DA 909	

SA CATEGORY I & II ILS- SPECIAL AIRCREW & AIRCRAFT CERTIFICATION REQUIRED

TDZ/CL Rwy 10R-28L
 HIRL Rwy 10R-28L and 10L-28R