


HHOOD FIVE ARRIVAL (RNAV) Transition Routes
(HHOOD.HHOOD5) 310CT24
PORTLAND, OREGON
PORTLAND INTL (PDX)

PORTLAND APP CON
124.35 299.2
D-ATIS
128.35 269.9
GND CON
121.9 348.6
PORTLAND TOWER
118.7 257.8 (Rwy 10L-28R)
123.775 251.125 (Rwys 3-21, 10R-28L)

RNAV 1 - DME/DME/IRU or GPS.
RADAR required.




HHOOD FIVE ARRIVAL (RNAV) Transition Routes
(HHOOD.HHOOD5) 24305
AL-330 (FAA)
PORTLAND INTL (PDX)
PORTLAND, OREGON

HHOOD FIVE ARRIVAL (RNAV)
(HHOOD:HHOOD5) 31OCT24

Arrival Routes

PORTLAND, OREGON
PORTLAND INTL (PDX)



ARRIVAL ROUTE DESCRIPTION

From HHOOD on track 256° to cross BEEVS at or above 7100, then on track 259° to BLRUN.

LANDING RUNWAYS 10L/R: From BLRUN on track 271° to cross SSDEE between 9000 and 11000, then on track 270° to cross THEID between 8000 and 10000 and at 240K, then on track 270° to cross EMZEY between 7000 and 8000 and at 230K, then on track 281° to cross CIZZL at or above 6000 and at 210K, then on track 281°. Expect RADAR vectors to final approach course.

LANDING RUNWAY 21: From BLRUN on track 279° to cross SOOZN at 8000 and at 210K, then on track 279°. Expect RADAR vectors to final approach course.

LANDING RUNWAYS 28L/R: From BLRUN on track 259° to cross SHAFR at 6700 and at 210K. Expect RNAV or ILS RWY 28L/R approach.

LOST COMMUNICATIONS

Maintain Rwy transition terminus altitude until established on approach procedure.

RUNWAYS 10L/R: After CIZZL, proceed to NNUTT, then left turn to BUXOM, conduct the ILS or LOC RWY 10L approach.

RUNWAY 21: After SOOZN turn right to CREAK and proceed on the LOC/DME RWY 21 approach.

RUNWAYS 28L/R: After SHAFR proceed on the ILS or LOC RWY 28R approach.

(HHOOD:HHOOD5) 24305

Arrival Routes

AL-330 (FAA)

PORTLAND INTL (PDX)
PORTLAND, OREGON