




LOM MW 223	APP CRS 085°	Rwy Idg TDZE Apt Elev	N/A N/A 957
----------------------	------------------------	-----------------------------	--

NDB-A

DAYTON/WRIGHT BROTHERS (MGY)

RADAR required for procedure entry.		MISSED APPROACH: Climb to 1800 then climbing right turn to 3000 direct MW LOM and hold.	
▼ ▲ NA	When local altimeter setting not received, use James M Cox Dayton Intl altimeter setting and increase all MDAs 60 feet, and Cat C/D visibilities ¼ SM.		
ASOS 118.375	COLUMBUS APP CON 118.85 269.275	CLNC DEL 119.4	UNICOM 122.8 (CTAF) 0



CATEGORY	A	B	C	D	FAF to MAP 4.4 NM					
 CIRCLING	1480-1	1520-1	1660-2	1660-2¼	Knots	60	90	120	150	180
	523 (600-1)	563 (600-1)	703 (800-2)	703 (800-2¼)	Min:Sec	4:24	2:56	2:12	1:46	1:28