

ILS or LOC RWY 21
ALTOONA/BLAIR COUNTY (A00)

MISSED APPROACH: Climb to 2100 then climbing right turn to 5000 on heading 295° and on JST R-096 to ZOTBI/JST 11.7 DME and hold, continue climb-in-hold to 5000.

CTAF
123.60