


VORTAC RIC	APP CRS	Rwy Ldg	9003
114.1	171°	TDZE	167
Chan 88		Apt Elev	167

VOR RWY 16
RICHMOND INTL (RIC)

DME or RADAR required. RADAR required for procedure entry.	MALSR	MISSED APPROACH: Climbing left turn to 2000 direct HPW VORTAC and hold.
Rwy 16 helicopter visibility reduction below RVR 4000 NA. For inop ALS, increase S-16 Cat A/B visibility to RVR 5500, and Cat C/D to 1 3/8 SM.		

ATIS	POTOMAC APP CON	RICHMOND TOWER	GND CON
119.15 263.025	126.4 282.375 (001°-185°) 126.75 307.2 (186°-360°)	121.1 257.8	121.9 348.6



VGSi and descent angles not coincident (VGSi Angle 3.00/TCH 71).				2000	HPW
MECHS RIC 11 RADAR				BILTT RIC 6 RADAR	
2000				2000	
5 NM				3.8 NM	1.3 NM
CATEGORY	A	B	C	D	
S-16	640/40 473 (500-3/4)			640/50 473 (500-1)	
CIRCLING	660-1	493 (500-1)	700-1 1/2 533 (600-1 1/2)	720-2 553 (600-2)	

ELEV 167	D	TDZE 167
171°		
TDZ/CL Rwy 34		
HIRL Rwy 2-20 and 16-34		
REIL Rwy 20		
FAF to MAP 5.1 NM		
Knots	60	90 120 150 180
Min:Sec	5:06	3:24 2:33 2:02 1:42